



CVE-2015-6391

Published on: 12/04/2015 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:17 PM UTC

CVE-2015-6391

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Unified Sip Phone 3900 Firmware](#) from [Cisco](#) contain the following vulnerability:

Cisco Unified SIP 3905 phones allow remote attackers to cause a denial of service (resource consumption and functionality loss) via a large amount of network traffic, aka Bug ID CSCuh51331.

CVE-2015-6391 has been assigned by [psirt@cisco.com](#) to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access Vector

Access Complexity

Authentication

NETWORK

LOW

NONE

Confidentiality Impact

Integrity Impact

Availability Impact

NONE

NONE

COMPLETE

CVE References

Description

Tags

Link

Cisco Unified SIP Phone 3905 Series Phones Let Remote Users Cause the Target System to Stop Functioning - SecurityTracker

[www.securitytracker.com](#)
[text/html](#)

[SECTrack 1034285](#)

Cisco SIP Phone 3905 Resource Limitation Denial of Service Vulnerability

[Vendor Advisory](#)
[tools.cisco.com](#)
[text/html](#)

[CISCO 20151202 Cisco SIP Phone 3905 Resource Limitation Denial of Service Vulnerability](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1(1b)	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1(2)	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1(2)sr1	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1(3)	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1(4)	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\1b\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\2\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\2\sr1	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\3\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\4\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	9.2(1)	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	9.2(2)	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	9.2\1\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	9.2\2\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\1b\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\2\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\2\sr1	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\3\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	8.1\4\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	9.2\1\	All	All	All
Operating System	Cisco	Unified Sip Phone 3900 Firmware	9.2\2\	All	All	All

cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(1b):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(2):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(2)sr1:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(3):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(4):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(1b):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(2):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(2)sr1:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(3):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(4):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:9.2(1):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:9.2(2):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:9.2(1):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:9.2(2):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(1b):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(2):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(2)sr1:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(3):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:8.1(4):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:9.2(1):*:~::~:
cpe:2.3:o:cisco:unified_sip_phone_3900_firmware:9.2(2):*:~::~:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)

