



CVE-2021-35114

Published on: Not Yet Published

Last Modified on: 06/22/2022 06:14:00 PM UTC


CVE-2021-35114

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Sa8540p](#) from [Qualcomm](#) contain the following vulnerability:

Improper buffer initialization on the backend driver can lead to buffer overflow in Snapdragon Auto

CVE-2021-35114 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) **Qualcomm, Inc. - Snapdragon Auto** version **SA8540P, SA9000P**

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.2 - HIGH**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Qualcomm Documentation	www.qualcomm.com text/html	CONFIRM www.qualcomm.com/company/product-security/bulletins/june-2022-bulletin

There are currently no QIDs associated with this CVE

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Qualcomm	Sa8540p	-	All	All	All
Operating System	Qualcomm	Sa8540p Firmware	-	All	All	All
Hardware	Qualcomm	Sa9000p	-	All	All	All
Operating System	Qualcomm	Sa9000p Firmware	-	All	All	All
<pre>cpe:2.3:h:qualcomm:sa8540p:-:*:*:*:*:*:</pre>						
<pre>cpe:2.3:o:qualcomm:sa8540p_firmware:-:*:*:*:*:*:</pre>						
<pre>cpe:2.3:h:qualcomm:sa9000p:-:*:*:*:*:*:</pre>						
<pre>cpe:2.3:o:qualcomm:sa9000p_firmware:-:*:*:*:*:*:</pre>						

No vendor comments have been submitted for this CVE

Source	Title	Posted (UTC)
@CVEreport	CVE-2021-35114 : Improper buffer initialization on the backend driver can lead to buffer overflow in Snapdragon Aut... twitter.com/i/web/status/1...	2022-06-14 09:48:53

Next ID→