



# CVE-2022-40102

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2022-40102
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2022-09-23 19:15:00 UTC
<b>Updated</b>	2022-09-27 04:37:00 UTC
<b>Description</b>	Tenda i9 v1.0.0.8(3828) was discovered to contain a buffer overflow via the formwrlSSIDset function. This vulnerability allow

## Risk And Classification

**Problem Types:** CWE-787

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Tenda</a>	<a href="#">I9</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">I9 Firmware</a>	1.0.0.8(3828)	All	All	All

## References

Reference	Source	Link
IOT_Vulnerability_Discovery/buffer_overflow_formwrlSSIDset.md at main · splashsc/IOT_Vulnerability_Discovery · GitHub	MISC	<a href="#">gith</a>
CVE Program record	CVE.ORG	<a href="#">ww</a>
NVD vulnerability detail	NVD	<a href="#">nvd</a>

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status [status.cve.report](#)**