




CVE-2004-2691

Published on: 12/31/2004 05:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:13 PM UTC

CVE-2004-2691

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [3c17205-us](#) from [3com](#) contain the following vulnerability:

Unspecified vulnerability in 3Com SuperStack 3 4400 switches with firmware version before 3.31 allows remote attackers to cause a denial of service (device reset) via a crafted request to the web management interface. NOTE: the provenance of this information is unknown; details are obtained from third party reports.

CVE-2004-2691 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **7.1 - HIGH**

Access
Vector

NETWORK

Access
Complexity

MEDIUM

Authentication

NONE

Confidentiality
Impact

NONE

Integrity
Impact

NONE

Availability
Impact

COMPLETE

CVE References

Description

Secunia - Advisories - 3Com SuperStack Switches HTTP Request Denial of Service

Tags

[Patch](#)
[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)

Link

[X SECUNIA 11934](#)

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](#)
[text/html](#)

[XF 3com-superstack-mngmt-dos\(16497\)](#)

No Description Provided

[www.osvdb.org](#)

[OSVDB 7246](#)

Inactive Link **Not Archived**

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further,

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	3com	3c17205-us	All	firmware_3.30	All	All
Hardware  	3com	3c17205-us	All	firmware_3.30	All	All
Hardware  	3com	3c17210-us	All	firmware_3.30	All	All
Hardware  	3com	3c17210-us	All	firmware_3.30	All	All
Hardware  	3com	Superstack 3 Switch	4400	firmware_3.30	All	All
Hardware  	3com	Superstack 3 Switch	4400_se	firmware_3.30	All	All
Hardware  	3com	Superstack 3 Switch	4400	firmware_3.30	All	All
Hardware  	3com	Superstack 3 Switch	4400_se	firmware_3.30	All	All
cpe:2.3:h:3com:3c17205-us:*.firmware_3.30:****.*.*:						
cpe:2.3:h:3com:3c17205-us:*.firmware_3.30:****.*.*:						
cpe:2.3:h:3com:3c17210-us:*.firmware_3.30:****.*.*:						
cpe:2.3:h:3com:3c17210-us:*.firmware_3.30:****.*.*:						
cpe:2.3:h:3com:superstack_3_switch:4400:firmware_3.30:****.*.*:						
cpe:2.3:h:3com:superstack_3_switch:4400_se:firmware_3.30:****.*.*:						
cpe:2.3:h:3com:superstack_3_switch:4400:firmware_3.30:****.*.*:						
cpe:2.3:h:3com:superstack_3_switch:4400_se:firmware_3.30:****.*.*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→