



CVE-2012-2469

Published on: 08/06/2012 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:26 PM UTC


CVE-2012-2469

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of **Nexus 7000** from **Cisco** contain the following vulnerability:

Cisco NX-OS 4.2, 5.0, 5.1, and 5.2 on Nexus 7000 series switches, when the High Availability (HA) policy is configured for Reset, allows remote attackers to cause a denial of service (device reset) via a malformed Cisco Discovery Protocol (CDP) packet, aka Bug IDs CSCtk34535 and CSCtk19132.

CVE-2012-2469 has been assigned by psirt@cisco.com to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access
Vector

Access
Complexity

Authentication

NETWORK

LOW

NONE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

NONE

NONE

COMPLETE

CVE References

Description

Tags

Link

Troubleshooting random Nexus reboots - TUan Pham Portal

web.archive.org
[text/html](#)
Inactive Link **Not Archived**

MISC www.4salesbyself.com/troubleshooting-random-nexus-reboots.aspx

Cisco Nexus 7000 Series NX-OS Release Notes, Release 5.2 [Cisco Nexus 7000 Series Switches] - Cisco Systems

Vendor Advisory
www.cisco.com
[text/html](#)

CONFIRM
www.cisco.com/en/US/docs/switches/datacenter/sw/5_x/nx-os/release/notes/52_nx-os_release_note.html

Cisco NX-OS CDP Packet Processing Flaw Lets Remote Users Deny Service - SecurityTracker

www.securitytracker.com
[text/html](#)

SECTRAK 1027352

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

cpe:2.3:h:cisco:nexus_7000_9-slot:-:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:
cpe:2.3:o:cisco:nx-os:4.2:*****:
cpe:2.3:o:cisco:nx-os:5.0:*****:
cpe:2.3:o:cisco:nx-os:5.1:*****:
cpe:2.3:o:cisco:nx-os:5.2:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report