




CVE-2015-3976

Published on: 08/28/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:09 PM UTC

CVE-2015-3976

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Multilink MI1200](#) from [Ge](#) contain the following vulnerability:

Cross-site scripting (XSS) vulnerability in GE Multilink ML810/3000/3100 series switch 5.2.0 and earlier, and GE Multilink ML800/1200/1600/2400 4.2.1 and earlier.

CVE-2015-3976 has been assigned by ics-cert@hq.dhs.gov to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **5.4 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	LOW	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVSS2 Score: **3.5 - LOW**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
GE Multilink Switch Vulnerabilities (Update A) ICS-CERT	Third Party Advisory US Government Resource ics-cert.us-cert.gov text/html	MISC ics-cert.us-cert.gov/advisories/ICSA-15-013-04A

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

Related QID Numbers

[591284](#) General Electric Multilink Switch Rivest Shamir Adleman (RSA) Private Key and Denial of Service (DoS) Multiple Vulnerabilities (ICSA-15-013-04A)

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Ge	Multilink MI1200	-	All	All	All
Hardware  	Ge	Multilink MI1200	-	All	All	All
Operating System	Ge	Multilink MI1200 Firmware	4.2.1	All	All	All
Operating System	Ge	Multilink MI1200 Firmware	4.2.1	All	All	All
Hardware  	Ge	Multilink MI1600	-	All	All	All
Hardware  	Ge	Multilink MI1600	-	All	All	All
Operating System	Ge	Multilink MI1600 Firmware	4.2.1	All	All	All
Operating System	Ge	Multilink MI1600 Firmware	4.2.1	All	All	All
Hardware  	Ge	Multilink MI2400	-	All	All	All
Hardware  	Ge	Multilink MI2400	-	All	All	All
Operating System	Ge	Multilink MI2400 Firmware	4.2.1	All	All	All
Operating System	Ge	Multilink MI2400 Firmware	4.2.1	All	All	All
Hardware  	Ge	Multilink MI3000	-	All	All	All
Hardware  	Ge	Multilink MI3000	-	All	All	All
Operating System	Ge	Multilink MI3000 Firmware	All	All	All	All
Hardware  	Ge	Multilink MI3100	-	All	All	All
Hardware  	Ge	Multilink MI3100	-	All	All	All
Operating System	Ge	Multilink MI3100 Firmware	All	All	All	All
Hardware  	Ge	Multilink MI800	-	All	All	All
Hardware  	Ge	Multilink MI800	-	All	All	All
Operating System	Ge	Multilink MI800 Firmware	4.2.1	All	All	All

Operating System	Ge	Multilink MI800 Firmware	4.2.1	All	All	All
Operating System	Ge	Multilink MI800 Firmware	4.2.1	All	All	All
Hardware 	Ge	Multilink MI810	-	All	All	All
Hardware 	Ge	Multilink MI810	-	All	All	All
Operating System	Ge	Multilink MI810 Firmware	5.2.0	All	All	All
Operating System	Ge	Multilink MI810 Firmware	5.2.0	All	All	All
cpe:2.3:h:ge:multilink_ml1200:-:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml1200:-:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml1200_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml1200_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml1600:-:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml1600:-:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml1600_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml1600_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml2400:-:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml2400:-:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml2400_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml2400_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml3000:-:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml3000:-:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml3000_firmware:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml3100:-:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml3100:-:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml3100_firmware:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml800:-:*:*:*:*:*:*:						
cpe:2.3:h:ge:multilink_ml800:-:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml800_firmware:4.2.1:*:*:*:*:*:*:						
cpe:2.3:o:ge:multilink_ml800_firmware:4.2.1:*:*:*:*:*:*:						

cpe:2.3:h:ge:multilink_ml810:-:*:*:*:*:*:

cpe:2.3:h:ge:multilink_ml810:-:*:*:*:*:*:

cpe:2.3:o:ge:multilink_ml810_firmware:5.2.0:*:*:*:*:*:

cpe:2.3:o:ge:multilink_ml810_firmware:5.2.0:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→