



CVE-2021-45392

Published on: Not Yet Published

Last Modified on: 02/23/2022 01:30:00 AM UTC


CVE-2021-45392

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Ax12](#) from [Tenda](#) contain the following vulnerability:

A Buffer Overflow vulnerability exists in Tenda Router AX12 V22.03.01.21_CN in the sub_422CE4 function in page /goform/setIPv6Status via the prefixDelegate parameter, which causes a Denial of Service.

CVE-2021-45392 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **7.8 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	COMPLETE

CVE References

Description	Tags	Link
AX12 AX3000双频千兆Wi-Fi 6无线路由器_腾达(Tenda)官方网站	www.tenda.com.cn text/html	MISC www.tenda.com.cn/product/AX12.html
腾达(Tenda)官方网站	www.tenda.com.cn text/html	MISC www.tenda.com.cn/

No Description Provided

tendawifi.com

MISC tendawifi.com/index.html

Inactive Link

Not Archived

IoT-CVE/Tenda/AX12/2 at main · sec-bin/loT-CVE · GitHub

github.com

text/html

MISC github.com/sec-bin/loT-CVE/tree/main/Tenda/AX12/2

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tenda	Ax12	-	All	All	All
Operating System	Tenda	Ax12 Firmware	22.03.01.21_cn	All	All	All

cpe:2.3:h:tenda:ax12:-:*****:

cpe:2.3:o:tenda:ax12_firmware:22.03.01.21_cn:*****:

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2021-45392 : A Buffer Overflow vulnerability exists in Tenda Router AX12 V22.03.01.21_CN in the sub_422CE4 func... twitter.com/i/web/status/1...	2022-02-14 17:06:13
 /r/netcve	CVE-2021-45392	2022-02-14 18:38:21

← Previous ID

Next ID →