




CVE-2022-29592

Published on: Not Yet Published

Last Modified on: 05/13/2022 04:25:00 AM UTC

CVE-2022-29592

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of **Tx9 Pro** from **Tenda** contain the following vulnerability:

Tenda TX9 Pro 22.03.02.10 devices allow OS command injection via `set_route` (called by `doSystemCmd_route`).

CVE-2022-29592 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **10 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Vulnerability/Tenda-TX9-V22.03.02.10-19042022-3.md at main · H4niz/Vulnerability · GitHub	github.com text/html	MISC github.com/H4niz/Vulnerability/blob/main/Tenda-TX9-V22.03.02.10-19042022-3.md

By selecting these links, you may be leaving CVEreport workspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that

are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tenda	Tx9 Pro	-	All	All	All
Operating System	Tenda	Tx9 Pro Firmware	22.03.02.10	All	All	All
cpe:2.3:h:tenda:tx9_pro:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:tx9_pro_firmware:22.03.02.10:~::~~::~~::~~::~~::~~::~~::						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @Robo_Alerts	Potentially Critical CVE Detected! CVE-2022-29592 Tenda TX9 Pro 22.03.02.10 devices allow OS command injection via... twitter.com/i/web/status/1...	2022-05-05 16:56:01
 @CVEreport	CVE-2022-29592 : Tenda TX9 Pro 22.03.02.10 devices allow OS command injection via set_route called by doSystemCmd_... twitter.com/i/web/status/1...	2022-05-05 17:23:31
 /r/netcve	CVE-2022-29592	2022-05-05 17:38:58

[← Previous ID](#)

[Next ID →](#)