




CVE-2022-40918

Published on: Not Yet Published

Last Modified on: 12/08/2022 03:51:00 PM UTC

CVE-2022-40918

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [Discovery Wifi U818a Hd Fpv](#) from [Force1rc](#) contain the following vulnerability:

Buffer overflow in firmware lewei_cam binary version 2.0.10 in Force 1 Discovery Wifi U818A HD+ FPV Drone allows attacker to gain remote code execution as root user via a specially crafted UDP packet. Please update the Reference section to these links > <http://thiscomputer.com/> > <https://www.bostoncyber.org/> >

<https://medium.com/@meekworth/exploiting-the-lw9621-drone-camera-module-773f00081368>

CVE-2022-40918 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVE References

Description	Tags	Link
	1af95112-6fd8-4c8f-8bd6-c47f8ef7b77a.filesusr.com application/pdf	MISC 1af95112-6fd8-4c8f-8bd6-c47f8ef7b77a.filesusr.com/ugd/c1f861_2bf7a43eda204c87ae7de972f4494590.
Exploiting the LW9621 Drone Camera Module by meekworth Medium	medium.com text/html	MISC medium.com/@meekworth/exploiting-the-lw9621-drone-camera-mod-773f00081368
	1af95112-6fd8-4c8f-8bd6-c47f8ef7b77a.filesusr.com application/pdf	MISC 1af95112-6fd8-4c8f-8bd6-c47f8ef7b77a.filesusr.com/ugd/c1f861_51eb0d33d5764efc93e9d5f19c306950.

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Force1rc	Discovery Wifi U818a Hd Fpv	-	All	All	All
Operating System	Force1rc	Discovery Wifi U818a Hd Fpv Firmware	2.0.10	All	All	All
cpe:2.3:h:force1rc:discovery_wifi_u818a_hd\+_fpv:-:*:*:*:*:*:						
cpe:2.3:o:force1rc:discovery_wifi_u818a_hd\+_fpv_firmware:2.0.10:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
@CVEreport	CVE-2022-40918 : Buffer overflow in firmware lewei_cam binary version 2.0.10 in Force 1 Discovery Wifi U818A HD+ FP... twitter.com/i/web/status/1...	2022-12-06 00:06:28
@Robo_Alerts	Potentially Critical CVE Detected! CVE-2022-40918 Buffer overflow in firmware lewei_cam binary version 2.0.10 in Fo... twitter.com/i/web/status/1...	2022-12-06 00:56:00
/r/netcve	CVE-2022-40918	2022-12-06 01:40:35

[← Previous ID](#)

[Next ID →](#)