



CVE-2023-43885

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2023-43885
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2023-11-07 08:15:00 UTC
Updated	2023-11-16 16:12:00 UTC
Description	Missing error handling in the HTTP server component of Tenda RX9 Pro Firmware V22.03.02.20 allows authenticated attac

Risk And Classification

Problem Types: CWE-862

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	Rx9 Pro	-	All	All	All
Operating System	Tenda	Rx9 Pro Firmware	22.03.02.10	All	All	All

References

Reference
Tenda RX9 PRO - Stack Overflow Vulnerability + DoS CVE-2023-43886 and CVE-2023-43885 – RTLCopyMemory – Software Security Engi
CVE Program record
NVD vulnerability detail

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report