CVE-2013-4863

Published on: 01/28/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:29 PM UTC

CVE-2013-4863

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Veralite from Micasaverde contain the following vulnerability:

The HomeAutomationGateway service in MiCasaVerde VeraLite with firmware 1.5.408 allows (1) remote attackers to execute arbitrary Lua code via a RunLua action in a request to upnp/control/hag on port 49451 or (2) remote authenticated users to execute arbitrary Lua code via a RunLua action in a request to port_49451/upnp/control/hag.

CVE-2013-4863 has been assigned by cve@mitre.org to track the vulnerability - currently rated as HIGH severity.

CVSS3 Score: 8.8 - HIGH

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	LOW	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 9 - HIGH

Access Vector	Access Complexity	Authentication
NETWORK	LOW	SINGLE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
	Exploit www3.trustwave.com text/plain	MISC www3.trustwave.com/spiderlabs/advisories/TWSL2013-019.txt

MiCasaVerde VeraLite 1.5.408 Traversal / Authorization / CSRF / Disclosure ≈ Packet Storm	Exploit Third Party Advisory VDB Entry packetstormsecurity.com text/html	MISC packetstormsecurity.com/files/122654/MiCasaVerde-VeraLite-1.5.408-Traversal-Authorization-CSRF-Disclosure.html
MiCasaVerde VeraLite 1.5.408 - Multiple Vulnerabilities	Exploit Third Party Advisory VDB Entry www.exploit-db.com Proof of Concept text/html	MISC www.exploit-db.com/exploits/27286

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Micasaverde	Veralite	-	All	All	All
Hardware	Micasaverde	Veralite	-	All	All	All
Operating System	Micasaverde	Veralite Firmware	1.5.408	All	All	All
Operating System	Micasaverde	Veralite Firmware	1.5.408	All	All	All

cpe:2.3:h:micasaverde:veralite:-:*:*:*:*:*:*:*:

cpe:2.3:h:micasaverde:veralite:-:*:*:*:*:*:*:*:

cpe:2.3:o:micasaverde:veralite_firmware:1.5.408:*:*:*:*:*:*:*:

cpe:2.3:o:micasaverde:veralite_firmware:1.5.408:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→