CVE-2014-0881

MITRE | NVD | CVE.ORG | Print: PDF

Summary

CVE	CVE-2014-0881
State	PUBLIC
Assigner	psirt@us.ibm.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-04-25 20:29:00 UTC
Updated	2018-06-04 13:20:00 UTC
Description	The TPM on Integrated Management Module II (IMM2) on IBM Flex System x222 servers with firmware 1.00 through 3.56 a

Risk And Classification

Problem Types: CWE-284

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Ibm	Flex System X222	-	All	All	All
Hardware	Ibm	Flex System X222	-	All	All	All
Operating System	Ibm	Integrated Management Module Firmware	All	All	All	All

References

Reference
IBM Support
Security Bulletin: TPM on the Integrated Management Module II (IMM2) of Flex System x222 compute node is not configured correctly (CVE-2
Security Bulletin: TPM on the Integrated Management Module II (IMM2) of Flex System x222 compute node is not configured correctly (CVE-2
CVE Program record
NVD vulnerability detail

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.