# CVE-2014-3936

MITRE | NVD | CVE.ORG | JSON API | Print: PDF

## Summary

| | |
|---|---|
| **CVE** | CVE-2014-3936 |
| **State** | PUBLIC |
| **Assigner** | cve@mitre.org |
| **Source Priority** | CVE Program / NVD first with legacy fallback |
| **Published** | 2014-06-02 14:55:00 UTC |
| **Updated** | 2023-04-26 19:27:00 UTC |
| **Description** | Stack-based buffer overflow in the do_hnap function in www/my_cgi.cgi in D-Link DSP-W215 (Rev. A1) with firmware 1.01b |

## Risk And Classification

**Problem Types:** CWE-119

## NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|---|---|---|---|---|---|---|
| Hardware | D-link | Dir-505l Shareport Mobile Companion | a1 | All | All | All |
| Hardware | D-link | Dir-505l Shareport Mobile Companion | a1 | All | All | All |
| Operating System | D-link | Dir505l Shareport Mobile Companion Firmware | All | All | All | All |
| Hardware | D-link | Dir505 Shareport Mobile Companion | a1 | All | All | All |
| Hardware | D-link | Dir505 Shareport Mobile Companion | a1 | All | All | All |
| Operating System | D-link | Dir505 Shareport Mobile Companion Firmware | All | All | All | All |
| Hardware | D-link | Dsp-w215 | a1 | All | All | All |
| Hardware | D-link | Dsp-w215 | a1 | All | All | All |
| Operating System | D-link | Dsp-w215 Firmware | All | b06 | All | All |
| Hardware | Dlink | Dir-505l Shareport Mobile Companion | a1 | All | All | All |
| Operating System | Dlink | Dir505l Shareport Mobile Companion Firmware | All | All | All | All |
| Hardware | Dlink | Dir505 Shareport Mobile Companion | a1 | All | All | All |
| Operating System | Dlink | Dir505 Shareport Mobile Companion Firmware | All | All | All | All |
| Hardware | Dlink | Dsp-w215 | a1 | All | All | All |
| Operating System | Dlink | Dsp-w215 Firmware | All | b06 | All | All |

## References

| Reference |
| --- |
| Security Advisory SA58972 - D-Link DIR-505 / DIR-505L Wireless Router HNAP "GetDeviceSettings" Buffer Overflow Vulnerability |
| D-Link Technical Support |
| D-Link HNAP Request Remote Buffer Overflow ≈ Packet Storm |
| DIR-505 and DIR-505L Stack Buffer Overflow Vulnerability |
| Hacking the D-Link DSP-W215 Smart Plug - /dev/ttyS0 |
| Security Advisory SA58728 - D-Link DSP-W215 Multiple Buffer Overflow Vulnerabilities - Secunia |
| D-Link Technical Support |
| CVE Program record |
| NVD vulnerability detail |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.



**Free CVE JSON API** cve.report/api

**CVE.report and Source URL Uptime Status** **status.cve.report**