CVE-2015-8306

Published on: 01/12/2016 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:12 PM UTC

CVE-2015-8306

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of P8 from Huawei contain the following vulnerability:

Buffer overflow in the HIFI driver in Huawei P8 phones with software GRA-TL00 before GRA-TL00C01B230, GRA-CL00 before GRA-CL00C92B230, GRA-CL10 before GRA-CL10C92B230, GRA-UL00 before GRA-UL00C00B230, and GRA-UL10 before GRA-UL10C00B230 allows attackers to cause a denial of service (system crash) or execute arbitrary code via an unspecified parameter.

CVE-2015-8306 has been assigned by cve@mitre.org to track the vulnerability - currently rated as HIGH severity.

CVSS3 Score: 7.8 - HIGH

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	NONE	REQUIRED
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 9.3 - HIGH

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Security Advisory - Buffer Overflow Vulnerability in HIFI Driver of Huawei Smart Phone	Vendor Advisory www.huawei.com text/html	CONFIRM www.huawei.com/en/psirt/security-advisories/huawei-sa-20160104-03-smartphone-en

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Huawei	P8	-	All	All	All
Hardware	Huawei	P8	-	All	All	All
Operating System	Huawei	P8 Firmware	gra-cl10	All	All	All
Operating System	Huawei	P8 Firmware	gra-cl100	All	All	All
Operating System	Huawei	P8 Firmware	gra-tl00	All	All	All
Operating System	Huawei	P8 Firmware	gra-ul10	All	All	All
Operating System	Huawei	P8 Firmware	gra-ul100	All	All	All
Operating System	Huawei	P8 Firmware	gra-cl10	All	All	All
Operating System	Huawei	P8 Firmware	gra-cl100	All	All	All
Operating System	Huawei	P8 Firmware	gra-tl00	All	All	All
Operating System	Huawei	P8 Firmware	gra-ul10	All	All	All
Operating System	Huawei	P8 Firmware	gra-ul100	All	All	All

cpe:2.3:h:huawei:p8:-:*:*:*:*:*:*:*:

cpe:2.3:h:huawei:p8:-:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-cl10:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-cl100:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-tl00:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-ul10:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-ul100:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-cl10:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-cl100:*:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-tl00:*:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-ul10:*:*:*:*:*:*:*:*:

cpe:2.3:o:huawei:p8_firmware:gra-ul100:*:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→