CVE-2018-15353

Published on: 08/17/2018 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:27 PM UTC

CVE-2018-15353

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of 24f2xg Router from Kraftway contain the following vulnerability:

A Buffer Overflow exploited through web interface by remote attacker can cause remote code execution in Kraftway 24F2XG Router firmware 3.5.30.1118.

CVE-2018-15353 has been assigned by vulnerability@kaspersky.com to track the vulnerability - currently rated as CRITICAL severity.

Affected Vendor/Software: **Kaspersky Lab** - **Kraftway** version **Kraftway 24F2XG Router firmware 3.5.30.1118**

CVSS3 Score: 9.8 - CRITICAL

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 10 - HIGH

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
KLCERT-18-009: Kraftway-24F2XG Router Possible Remote Code Execution | Kaspersky ICS	VDB Entry ics-cert.kaspersky.com	MISC ics-cert.kaspersky.com/advisories/klcert-advisories/2018/08/17/klcert-18-009-kraftway-24f2xg-router-

Possible Remote Code Execution | Kaspersky ICS CERT	text/html	possible-remote-code-execution/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Kraftway	24f2xg Router	-	All	All	All
Hardware	Kraftway	24f2xg Router	-	All	All	All
Operating System	Kraftway	24f2xg Router Firmware	All	All	All	All

cpe:2.3:h:kraftway:24f2xg_router:-:*:*:*:*:*:*:*:

cpe:2.3:h:kraftway:24f2xg_router:-:*:*:*:*:*:*:*:

cpe:2.3:o:kraftway:24f2xg_router_firmware:*:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→