CVE-2018-17768

Published on: 09/09/2020 12:00:00 AM UTC

Last Modified on: 10/07/2022 06:36:00 PM UTC

CVE-2018-17768

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Telium 2 from Ingenico contain the following vulnerability:

Ingenico Telium 2 POS terminals have an insecure TRACE protocol. This is fixed in Telium 2 SDK v9.32.03 patch N.

CVE-2018-17768 has been assigned by cve@mitre.org to track the vulnerability - currently rated as MEDIUM severity.

CVSS3 Score: 6.8 - MEDIUM

Attack Vector	Attack Complexity	Privileges Required	User Interaction
PHYSICAL	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 7.2 - HIGH

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Ingenico Group - Smart Terminals - Telium2	Product, ingenico.us, text/html	MISC ingenico.us/smart-terminals/telium2
DEF CON Safe Mode Payment Village - Aleksei Stennikov - PoS	Exploit	MISC youtu.be/gtbS3Gr264w

Terminal Security Uncovered - YouTube	Third Party Advisory youtu.be text/html	
PoS Terminal Security Uncovered - Aleksei Stennikov - YouTube	Exploit Third Party Advisory youtu.be text/html	MISC youtu.be/oyUD7RDJsJs
PT-2020-13: Insecure TRACE protocol	www.ptsecurity.com text/html	MISC www.ptsecurity.com/ww-en/analytics/threatscape/pt-2020-13/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Ingenico	Telium 2	-	All	All	All
Hardware	Ingenico	Telium 2	-	All	All	All
Operating System	Ingenico	Telium 2 Firmware	All	All	All	All
Operating System	Ingenico	Telium 2 Firmware	All	All	All	All

cpe:2.3:h:ingenico:telium_2:-:*:*:*:*:*:*:*:

cpe:2.3:h:ingenico:telium_2:-:*:*:*:*:*:*:*:

cpe:2.3:o:ingenico:telium_2_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:o:ingenico:telium_2_firmware:*:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→