# CVE-2019-0136

MITRE | NVD | CVE.ORG | Print: PDF

## Summary

| | |
|---|---|
| **CVE** | CVE-2019-0136 |
| **State** | PUBLIC |
| **Assigner** | secure@intel.com |
| **Source Priority** | CVE Program / NVD first with legacy fallback |
| **Published** | 2019-06-13 16:29:00 UTC |
| **Updated** | 2020-08-24 17:37:00 UTC |
| **Description** | Insufficient access control in the Intel(R) PROSet/Wireless WiFi Software driver before version 21.10 may allow an unauthe |

## Risk And Classification

**Problem Types:** NVD-CWE-noinfo

## NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|---|---|---|---|---|---|---|
| Operating System | Google | Chrome Os | - | All | All | All |
| Operating System | Google | Chrome Os | - | All | All | All |
| Application | Intel | Proset/wireless Wifi | All | All | All | All |
| Application | Intel | Proset/wireless Wifi | All | All | All | All |
| Application | Intel | Proset/wireless Wifi | All | All | All | All |
| Operating System | Linux | Linux Kernel | - | All | All | All |
| Operating System | Linux | Linux Kernel | - | All | All | All |
| Operating System | Microsoft | Windows 10 | - | All | All | All |
| Operating System | Microsoft | Windows 10 | - | All | All | All |
| Operating System | Microsoft | Windows 7 | - | All | All | All |
| Operating System | Microsoft | Windows 7 | - | All | All | All |
| Operating System | Microsoft | Windows 8.1 | - | All | All | All |
| Operating System | Microsoft | Windows 8.1 | - | All | All | All |

## References

| Reference | Source | Link | Tags |
|---|---|---|---|
| Page Not Found - Lenovo Support US | CONFIRM | support.lenovo.com | Third Part |

| | | | |
|---|---|---|---|
| [SECURITY] [DLA 1930-1] linux security update | MLIST | lists.debian.org | |
| Malformed Request | BID | www.securityfocus.com | Third Part |
| [SECURITY] [DLA 2114-1] linux-4.9 security update | MLIST | lists.debian.org | |
| USN-4118-1: Linux kernel (AWS) vulnerabilities \| Ubuntu security notices \| Ubuntu | UBUNTU | usn.ubuntu.com | |
| INTEL-SA-00232 | CONFIRM | www.intel.com | |
| USN-4115-1: Linux kernel vulnerabilities \| Ubuntu security notices \| Ubuntu | UBUNTU | usn.ubuntu.com | |
| [SECURITY] [DLA 1919-2] linux-4.9 security update | MLIST | lists.debian.org | |
| Kernel Live Patch Security Notice LSN-0058-1 ≈ Packet Storm | MISC | packetstormsecurity.com | |
| [SECURITY] [DLA 1919-1] linux-4.9 security update | MLIST | lists.debian.org | |
| USN-4147-1: Linux kernel vulnerabilities \| Ubuntu security notices \| Ubuntu | UBUNTU | usn.ubuntu.com | |
| JVN#75617741: Intel Dual Band Wireless-AC 8260 vulnerable to denial-of-service (DoS) | JVN | jvn.jp | |
| USN-4145-1: Linux kernel vulnerabilities \| Ubuntu security notices | UBUNTU | usn.ubuntu.com | |
| CVE Program record | CVE.ORG | www.cve.org | canonical |
| NVD vulnerability detail | NVD | nvd.nist.gov | canonical |

No vendor comments have been submitted for this CVE.

## Legacy QID Mappings

- 671064 EulerOS Security Update for kernel (EulerOS-SA-2019-2599)
- 751684 SUSE Enterprise Linux Security Update for the Linux Kernel (Live Patch 41 for SLE 12 SP3) (SUSE-SU-2022:0329-1)
- 751687 SUSE Enterprise Linux Security Update for the Linux Kernel (Live Patch 40 for SLE 12 SP3) (SUSE-SU-2022:0328-1)
- 751688 SUSE Enterprise Linux Security Update for the Linux Kernel (Live Patch 37 for SLE 12 SP3) (SUSE-SU-2022:0325-1)
- 751689 SUSE Enterprise Linux Security Update for the Linux Kernel (Live Patch 39 for SLE 12 SP3) (SUSE-SU-2022:0327-1)
- 751698 SUSE Enterprise Linux Security Update for the Linux Kernel (SUSE-SU-2022:0362-1)
- 753441 SUSE Enterprise Linux Security Update for the Linux Kernel (SUSE-SU-2022:14905-1)