CVE-2019-13651

Published on: 10/24/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:46 PM UTC

CVE-2019-13651

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of M7350 from Tp-link contain the following vulnerability:

TP-Link M7350 devices through 1.0.16 Build 181220 Rel.1116n allow portMappingProtocol OS Command Injection (issue 3 of 5).

CVE-2019-13651 has been assigned by cve@mitre.org to track the vulnerability - currently rated as CRITICAL severity.

CVSS3 Score: 9.8 - CRITICAL

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 10 - HIGH

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Pastebin.com - Not Found (#404)	Exploit, Third Party Advisory, pastebin.com, text/html, Inactive Link, Not Archived	MISC pastebin.com/yAxBFe05

WiFi Networking Equipment for Home & Business | TP-Link	Product www.tp-link.com text/html	MISC www.tp-link.com

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tp-link	M7350	-	All	All	All
Hardware	Tp-link	M7350	-	All	All	All
Operating System	Tp-link	M7350 Firmware	All	All	All	All

cpe:2.3:h:tp-link:m7350:-:*:*:*:*:*:*:*:

cpe:2.3:h:tp-link:m7350:-:*:*:*:*:*:*:*:

cpe:2.3:o:tp-link:m7350_firmware:*:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→