# CVE-2020-28373

MITRE | NVD | CVE.ORG | Print: PDF

## Summary

| | |
|---|---|
| **CVE** | CVE-2020-28373 |
| **State** | PUBLIC |
| **Assigner** | cve@mitre.org |
| **Source Priority** | CVE Program / NVD first with legacy fallback |
| **Published** | 2020-11-09 22:15:00 UTC |
| **Updated** | 2020-11-23 18:41:00 UTC |
| **Description** | upnpd on certain NETGEAR devices allows remote (LAN) attackers to execute arbitrary code via a stack-based buffer over |

## Risk And Classification

**Problem Types:** CWE-787

## NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|---|---|---|---|---|---|---|
| Hardware | Netgear | R6250 | - | All | All | All |
| Hardware | Netgear | R6250 | - | All | All | All |
| Operating System | Netgear | R6250 Firmware | 1.0.4.44 | All | All | All |
| Operating System | Netgear | R6250 Firmware | 1.0.4.44 | All | All | All |
| Hardware | Netgear | R6400 | - | All | All | All |
| Hardware | Netgear | R6400 | - | All | All | All |
| Hardware | Netgear | R6400v2 | - | All | All | All |
| Hardware | Netgear | R6400v2 | - | All | All | All |
| Operating System | Netgear | R6400v2 Firmware | 1.0.4.102_10.0.75 | All | All | All |
| Operating System | Netgear | R6400v2 Firmware | 1.0.4.102_10.0.75 | All | All | All |
| Operating System | Netgear | R6400 Firmware | 1.0.1.62_1.0.41 | All | All | All |
| Operating System | Netgear | R6400 Firmware | 1.0.1.62_1.0.41 | All | All | All |
| Hardware | Netgear | R7000p | - | All | All | All |
| Hardware | Netgear | R7000p | - | All | All | All |
| Operating System | Netgear | R7000p Firmware | 1.3.2.126_10.1.66 | All | All | All |
| Operating System | Netgear | R7000p Firmware | 1.3.2.126_10.1.66 | All | All | All |
| Hardware | Netgear | R7300dst | - | All | All | All |

| | | | | | | |
|---|---|---|---|---|---|---|
| Hardware | Netgear | R7300dst | - | All | All | All |
| Operating System | Netgear | R7300dst Firmware | 1.0.0.74 | All | All | All |
| Operating System | Netgear | R7300dst Firmware | 1.0.0.74 | All | All | All |
| Hardware | Netgear | R7850 | - | All | All | All |
| Hardware | Netgear | R7850 | - | All | All | All |
| Operating System | Netgear | R7850 Firmware | 1.0.5.64 | All | All | All |
| Operating System | Netgear | R7850 Firmware | 1.0.5.64 | All | All | All |
| Hardware | Netgear | R7900 | - | All | All | All |
| Hardware | Netgear | R7900 | - | All | All | All |
| Operating System | Netgear | R7900 Firmware | 1.0.4.30 | All | All | All |
| Operating System | Netgear | R7900 Firmware | 1.0.4.30 | All | All | All |
| Hardware | Netgear | R8000 | - | All | All | All |
| Hardware | Netgear | R8000 | - | All | All | All |
| Operating System | Netgear | R8000 Firmware | 1.0.4.62 | All | All | All |
| Operating System | Netgear | R8000 Firmware | 1.0.4.62 | All | All | All |
| Hardware | Netgear | R8300 | - | All | All | All |
| Hardware | Netgear | R8300 | - | All | All | All |
| Operating System | Netgear | R8300 Firmware | 1.0.2.136 | All | All | All |
| Operating System | Netgear | R8300 Firmware | 1.0.2.136 | All | All | All |
| Hardware | Netgear | R8500 | - | All | All | All |
| Hardware | Netgear | R8500 | - | All | All | All |
| Operating System | Netgear | R8500 Firmware | 1.0.2.136 | All | All | All |
| Operating System | Netgear | R8500 Firmware | 1.0.2.136 | All | All | All |
| Hardware | Netgear | Rax20 | - | All | All | All |
| Hardware | Netgear | Rax20 | - | All | All | All |
| Operating System | Netgear | Rax20 Firmware | 1.0.2.64 | All | All | All |
| Operating System | Netgear | Rax20 Firmware | 1.0.2.64 | All | All | All |
| Hardware | Netgear | Rax80 | - | All | All | All |
| Hardware | Netgear | Rax80 | - | All | All | All |
| Operating System | Netgear | Rax80 Firmware | 1.0.3.102 | All | All | All |
| Operating System | Netgear | Rax80 Firmware | 1.0.3.102 | All | All | All |
| Hardware | Netgear | Xr300 | - | All | All | All |
| Hardware | Netgear | Xr300 | - | All | All | All |
| Operating System | Netgear | Xr300 Firmware | 1.0.3.50_10.3.36 | All | All | All |
| Operating System | Netgear | Xr300 Firmware | 1.0.3.50_10.3.36 | All | All | All |

## References

| Reference | Source | Link | Tags |
|---|---|---|---|
| Page not found · GitHub · GitHub | MISC | github.com | Broken Link, Third Party Advisory |
| CVE Program record | CVE.ORG | www.cve.org | canonical |
| NVD vulnerability detail | NVD | nvd.nist.gov | canonical, analysis |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.