CVE-2020-3675

Published on: 09/08/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:23:40 PM UTC

CVE-2020-3675

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Ipq5018 from Qualcomm contain the following vulnerability:

u'Potential integer underflow while parsing Service Info and IPv6 link-local TLVs that comes as part of NDPE attribute' in Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking in IPQ5018, IPQ6018, IPQ8074, Kamorta, Nicobar, QCA6390, QCN7605, QCS404, QCS405, Rennell, SA415M, Saipan, SC7180, SC8180X, SDX55, SM6150, SM7150, SM8150, SM8250

CVE-2020-3675 has been assigned by product-security@qualcomm.com to track the vulnerability - currently rated as CRITICAL severity.

Affected Vendor/Software: **Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking** version **IPQ5018, IPQ6018, IPQ8074, Kamorta, Nicobar, QCA6390, QCN7605, QCS404, QCS405, Rennell, SA415M, Saipan, SC7180, SC8180X, SDX55, SM6150, SM7150, SM8150, SM8250**

CVSS3 Score: 9.8 - CRITICAL

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 10 - HIGH

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**

COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
August 2020 Security Bulletin | Qualcomm	Broken Link Vendor Advisory www.qualcomm.com text/html	CONFIRM www.qualcomm.com/company/product-security/bulletins/august-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Qualcomm	Ipq5018	-	All	All	All
Hardware	Qualcomm	Ipq5018	-	All	All	All
Operating System	Qualcomm	Ipq5018 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq5018 Firmware	-	All	All	All
Hardware	Qualcomm	Ipq6018	-	All	All	All
Hardware	Qualcomm	Ipq6018	-	All	All	All
Operating System	Qualcomm	Ipq6018 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq6018 Firmware	-	All	All	All
Hardware	Qualcomm	Ipq8074	-	All	All	All
Hardware	Qualcomm	Ipq8074	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Hardware	Qualcomm	Kamorta	-	All	All	All
Hardware	Qualcomm	Kamorta	-	All	All	All
Operating System	Qualcomm	Kamorta Firmware	-	All	All	All
Operating System	Qualcomm	Kamorta Firmware	-	All	All	All

Hardware	Qualcomm	Nicobar	-	All	All	All
Hardware	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware	Qualcomm	Qca6390	-	All	All	All
Hardware	Qualcomm	Qca6390	-	All	All	All
Operating System	Qualcomm	Qca6390 Firmware	-	All	All	All
Operating System	Qualcomm	Qca6390 Firmware	-	All	All	All
Hardware	Qualcomm	Qcn7605	-	All	All	All
Hardware	Qualcomm	Qcn7605	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Hardware	Qualcomm	Qcs404	-	All	All	All
Hardware	Qualcomm	Qcs404	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Hardware	Qualcomm	Qcs405	-	All	All	All
Hardware	Qualcomm	Qcs405	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Hardware	Qualcomm	Rennell	-	All	All	All
Hardware	Qualcomm	Rennell	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Hardware	Qualcomm	Sa415m	-	All	All	All
Hardware	Qualcomm	Sa415m	-	All	All	All
Operating	Qualcomm	Sa415m Firmware	-	All	All	All

System						
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All
Hardware	Qualcomm	Saipan	-	All	All	All
Hardware	Qualcomm	Saipan	-	All	All	All
Operating System	Qualcomm	Saipan Firmware	-	All	All	All
Operating System	Qualcomm	Saipan Firmware	-	All	All	All
Hardware	Qualcomm	Sc7180	-	All	All	All
Hardware	Qualcomm	Sc7180	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Operating System	Qualcomm	Sc7180 Firmware	-	All	All	All
Hardware	Qualcomm	Sc8180x	-	All	All	All
Hardware	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware	Qualcomm	Sdx55	-	All	All	All
Hardware	Qualcomm	Sdx55	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Hardware	Qualcomm	Sm6150	-	All	All	All
Hardware	Qualcomm	Sm6150	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware	Qualcomm	Sm7150	-	All	All	All
Hardware	Qualcomm	Sm7150	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware	Qualcomm	Sm8150	-	All	All	All

Hardware	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware	Qualcomm	Sm8250	-	All	All	All
Hardware	Qualcomm	Sm8250	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All

cpe:2.3:h:qualcomm:ipq5018:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq5018:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:ipq5018_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:ipq5018_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq6018:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq6018:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:ipq6018_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:ipq6018_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:kamorta:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:kamorta:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:kamorta_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:kamorta_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6390:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6390:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qca6390_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qca6390_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs404:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs404:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qcs404_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qcs404_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qcs405_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:qcs405_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sa415m:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sa415m:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sa415m_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sa415m_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:saipan:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:saipan:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:saipan_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:saipan_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc7180:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdx55:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sdx55_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm6150:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm6150_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm7150_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm7150_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm8150:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm8150:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm8150_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm8150_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm8250:-:*:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sm8250:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm8250_firmware:-:*:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm8250_firmware:-:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

© CVE.report 2023 |
Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registred trademarks of The MITRE Corporation and the authoritative source of CVE content is MITRE's CVE web site. This site includes MITRE data granted under the following license.

CVE.report and Source URL Uptime Status status.cve.report