# CVE-2020-7801

MITRE | NVD | CVE.ORG | JSON API | Print: PDF

## Summary

| | |
|---|---|
| **CVE** | CVE-2020-7801 |
| **State** | PUBLIC |
| **Assigner** | cve@mitre.org |
| **Source Priority** | CVE Program / NVD first with legacy fallback |
| **Published** | 2020-04-14 17:15:00 UTC |
| **Updated** | 2020-04-14 18:55:00 UTC |
| **Description** | The Synergy Systems & Solutions (SSS) HUSKY RTU 6049-E70, with firmware Versions 5.0 and prior, has an Exposure of |

## Risk And Classification

**Problem Types:** CWE-200

## NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|---|---|---|---|---|---|---|
| Hardware | Mysyngeryss | Husky Rtu 6049-e70 | - | All | All | All |
| Hardware | Mysyngeryss | Husky Rtu 6049-e70 | - | All | All | All |
| Operating System | Mysyngeryss | Husky Rtu 6049-e70 Firmware | All | All | All | All |

## References

| Reference | Source | Link | Tags |
|---|---|---|---|
| Synergy Systems & Solutions HUSKY RTU (Update A) \| CISA | MISC | www.us-cert.gov | Third Party Advisory, US Government Resou |
| CVE Program record | CVE.ORG | www.cve.org | canonical |
| NVD vulnerability detail | NVD | nvd.nist.gov | canonical, analysis |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

**Free CVE JSON API** cve.report/api

**CVE.report and Source URL Uptime Status status.cve.report**