# CVE-2021-38538

MITRE | NVD | CVE.ORG | Print: PDF

## Summary

| | |
|---|---|
| **CVE** | CVE-2021-38538 |
| **State** | PUBLIC |
| **Assigner** | cve@mitre.org |
| **Source Priority** | CVE Program / NVD first with legacy fallback |
| **Published** | 2021-08-11 00:17:00 UTC |
| **Updated** | 2021-08-19 15:31:00 UTC |
| **Description** | Certain NETGEAR devices are affected by stored XSS. This affects D7800 before 1.0.1.56, R7800 before 1.0.2.68, R8900 |

## Risk And Classification

**Problem Types:** CWE-79

## NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|---|---|---|---|---|---|---|
| Hardware | Netgear | D7800 | - | All | All | All |
| Operating System | Netgear | D7800 Firmware | All | All | All | All |
| Hardware | Netgear | R7800 | - | All | All | All |
| Operating System | Netgear | R7800 Firmware | All | All | All | All |
| Hardware | Netgear | R8900 | - | All | All | All |
| Operating System | Netgear | R8900 Firmware | All | All | All | All |
| Hardware | Netgear | R9000 | - | All | All | All |
| Operating System | Netgear | R9000 Firmware | All | All | All | All |
| Hardware | Netgear | Rax120 | - | All | All | All |
| Operating System | Netgear | Rax120 Firmware | All | All | All | All |
| Hardware | Netgear | Rbk20 | - | All | All | All |
| Operating System | Netgear | Rbk20 Firmware | All | All | All | All |
| Hardware | Netgear | Rbk40 | - | All | All | All |
| Operating System | Netgear | Rbk40 Firmware | All | All | All | All |
| Hardware | Netgear | Rbk50 | - | All | All | All |
| Operating System | Netgear | Rbk50 Firmware | All | All | All | All |
| Hardware | Netgear | Rbr20 | - | All | All | All |

| | | | | | | |
|---|---|---|---|---|---|---|
| Operating System | Netgear | Rbr20 Firmware | All | All | All | All |
| Hardware | Netgear | Rbr40 | - | All | All | All |
| Operating System | Netgear | Rbr40 Firmware | All | All | All | All |
| Hardware | Netgear | Rbr50 | - | All | All | All |
| Operating System | Netgear | Rbr50 Firmware | All | All | All | All |
| Hardware | Netgear | Rbs20 | - | All | All | All |
| Operating System | Netgear | Rbs20 Firmware | All | All | All | All |
| Hardware | Netgear | Rbs40 | - | All | All | All |
| Operating System | Netgear | Rbs40 Firmware | All | All | All | All |
| Hardware | Netgear | Rbs50 | - | All | All | All |
| Operating System | Netgear | Rbs50 Firmware | All | All | All | All |
| Hardware | Netgear | Xr500 | - | All | All | All |
| Operating System | Netgear | Xr500 Firmware | All | All | All | All |

## References

| Reference |
|---|
| Security Advisory for Stored Cross Site Scripting on Some Routers, Gateways, and WiFi Systems , PSV-2018-0515 \| Answer \| NETGEAR Sup |
| CVE Program record |
| NVD vulnerability detail |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.