CVE-2021-4105

Published on: Not Yet Published

Last Modified on: 07/07/2023 07:20:00 PM UTC

CVE-2021-4105 - advisory for TR-23-0108

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Coslat Bx5s1d3 from Bg-tek contain the following vulnerability:

Improper Handling of Parameters vulnerability in BG-TEK COSLAT Firewall allows Remote Code Inclusion.This issue affects COSLAT Firewall: from 5.24.0.R.20180630 before 5.24.0.R.20210727.

CVE-2021-4105 has been assigned by cve@usom.gov.tr to track the vulnerability - currently rated as CRITICAL severity.

Affected Vendor/Software: **BG-TEK** - **COSLAT Firewall** version **< 5.24.0.r.20210727**

CVSS3 Score: 9.8 - CRITICAL

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	HIGH	HIGH

CVE References

Description	Tags	Link
Ulusal Siber Olaylara Müdahale Merkezi - USOM	www.usom.gov.tr text/html	MISC www.usom.gov.tr/bildirim/tr-23-0108
ÖNEMLİ: Kritik Güncelleme - 27-07-2021 tarihinde yayınlanan güncelleme içeriği ~ Coslat Firewall Blog	blog.coslat.com text/html	MISC blog.coslat.com/2021/07/onemli-kritik-guncelleme-2021-07-27.html

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Bg-tek	Coslat Bx5s1d3	-	All	All	All
Operating System	Bg-tek	Coslat Bx5s1d3 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Bx5s1d4	-	All	All	All
Operating System	Bg-tek	Coslat Bx5s1d4 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Bx5s1d5	-	All	All	All
Operating System	Bg-tek	Coslat Bx5s1d5 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Rm1ds1000	-	All	All	All
Operating System	Bg-tek	Coslat Rm1ds1000 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Rm2ds2000	-	All	All	All
Operating System	Bg-tek	Coslat Rm2ds2000 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Rm2s200	-	All	All	All
Operating System	Bg-tek	Coslat Rm2s200 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Rm3s300	-	All	All	All
Operating System	Bg-tek	Coslat Rm3s300 Firmware	All	All	All	All
Hardware	Bg-tek	Coslat Rm4s500	-	All	All	All
Operating System	Bg-tek	Coslat Rm4s500 Firmware	All	All	All	All

cpe:2.3:h:bg-tek:coslat_bx5s1d3:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_bx5s1d3_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_bx5s1d4:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_bx5s1d4_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_bx5s1d5:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_bx5s1d5_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_rm1ds1000:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_rm1ds1000_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_rm2ds2000:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_rm2ds2000_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_rm2s200:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_rm2s200_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_rm3s300:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_rm3s300_firmware:*:*:*:*:*:*:*:*:

cpe:2.3:h:bg-tek:coslat_rm4s500:-:*:*:*:*:*:*:*:

cpe:2.3:o:bg-tek:coslat_rm4s500_firmware:*:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
@CVEreport	CVE-2021-4105 : Improper Handling of Parameters vulnerability in BG-TEK COSLAT Firewall allows Remote Code Inclusio… twitter.com/i/web/status/1…	2023-02-24 12:09:52
/r/netcve	CVE-2021-4105	2023-02-24 13:38:13

← Previous ID

Next ID→