CVE-2022-25584

Published on: Not Yet Published

Last Modified on: 08/08/2023 02:22:00 PM UTC

CVE-2022-25584

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Fw3170-ps-e from Flexwatch contain the following vulnerability:

Seyeon Tech Co., Ltd FlexWATCH FW3170-PS-E Network Video System 4.23-3000_GY allows attackers to access sensitive information.

CVE-2022-25584 has been assigned by cve@mitre.org to track the vulnerability - currently rated as HIGH severity.

CVSS3 Score: 7.5 - HIGH

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: 5 - MEDIUM

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
Network Video System - Live View	115.142.194.178 text/html	MISC 115.142.194.178:10001/app/multi/single.asp
Network Video System - Live View	183.100.61.196 text/html	MISC 183.100.61.196:10001/app/multi/single.asp

Document Error: Site or Page Not Found	115.142.194.178 text/html Inactive Link Not Archived	MISC 115.142.194.178:10001/app/multi/single.asp.ad
Network Video System - Live View	211.36.62.253 text/html	MISC 211.36.62.253:10001/app/multi/single.asp
Network Video System - Live View	210.223.145.159 text/html	MISC 210.223.145.159:10001/app/multi/single.asp
GitHub - NSSCYCTFER/Flexwatch: Flexwatch-CVE	github.com text/html	MISC github.com/NSSCYCTFER/Flexwatch
Network Video System - Live View	211.174.227.102 text/html	MISC 211.174.227.102:10001/app/multi/single.asp
Network Video System - Live View	211.240.10.38 text/html	MISC 211.240.10.38:10001/app/multi/single.asp
Document Error: Site or Page Not Found	211.174.227.102 text/html Inactive Link Not Archived	MISC 211.174.227.102:10001/app/multi/single.asp.aa
Document Error: Site or Page Not Found	211.240.10.38 text/html Inactive Link Not Archived	MISC 211.240.10.38:10001/app/multi/single.asp.ab
Network Video System - Live View	27.1.124.18 text/html	MISC 27.1.124.18:10001/app/multi/single.asp
No Description Provided	118.176.196.247 Inactive Link Not Archived	MISC 118.176.196.247:10001/app/multi/single.asp
Network Video System - Live View	211.174.227.230 text/html	MISC 211.174.227.230:10001/app/multi/single.asp
Document Error: Site or Page Not Found	121.133.21.35 text/html Inactive Link Not Archived	MISC 121.133.21.35:10001/app/multi/single.asp.ac
Network Video System - Live View	121.133.21.35 text/html	MISC 121.133.21.35:10001/app/multi/single.asp

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Flexwatch	Fw3170-ps-e	-	All	All	All
Operating System	Flexwatch	Fw3170-ps-e Firmware	4.23-3000_gy	All	All	All

cpe:2.3:h:flexwatch:fw3170-ps-e:-:*:*:*:*:*:*:*:

cpe:2.3:o:flexwatch:fw3170-ps-e_firmware:4.23-3000_gy:*:*:*:*:*:*:*:

cpe:2.3:o:flexwatch:fw3170-ps-e_firmware:4.23-3000_gy:*:*:*:*:*:*:*

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
@CVEreport	CVE-2022-25584 : Seyeon Tech Co., Ltd FlexWATCH FW3170-PS-E Network Video System 4.23-3000_GY allows attackers to a… twitter.com/i/web/status/1…	2022-04-05 01:03:09
/r/netcve	CVE-2022-25584	2022-04-05 01:39:11

← Previous ID

Next ID→