CVE-2022-30326

Published on: Not Yet Published

Last Modified on: 06/27/2022 07:12:00 PM UTC

CVE-2022-30326

Source: Mitre | Source: NIST | CVE.ORG | Print: PDF



Certain versions of Tew-831dr from Trendnet contain the following vulnerability:

An issue was found on TRENDnet TEW-831DR 1.0 601.130.1.1356 devices. The network pre-shared key field on the web interface is vulnerable to XSS. An attacker can use a simple XSS payload to crash the basic.config page of the web interface.

CVE-2022-30326 has been assigned by cve@mitre.org to track the vulnerability - currently rated as MEDIUM severity.

CVSS3 Score: 5.4 - MEDIUM

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	LOW	REQUIRED
Scope	**Confidentiality Impact**	**Integrity Impact**	**Availability Impact**
CHANGED	LOW	LOW	NONE

CVSS2 Score: 3.5 - LOW

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	SINGLE
Confidentiality Impact	**Integrity Impact**	**Availability Impact**
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
NCC Group Research – Making the world safer and more secure	research.nccgroup.com text/html	MISC research.nccgroup.com/?research=Technical+advisories
Technical Advisory – Multiple Vulnerabilities in Trendnet TEW-831DR WiFi Router (CVE-2022-30325, CVE-2022-30326, CVE-	research.nccgroup.com text/html	MISC research.nccgroup.com/2022/06/10/technical-

2022-30327, CVE-2022-30328, CVE-2022-30329) – NCC Group Research	advisory-multiple-vulnerabilities-in-trendnet-tew-831dr-wifi-router-cve-2022-30325-cve-2022-30326-cve-2022-30327-cve-2022-30328-cve-2022-30329/

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Trendnet	Tew-831dr	-	All	All	All
Operating System	Trendnet	Tew-831dr Firmware	1.0_601.130.1.1356	All	All	All

cpe:2.3:h:trendnet:tew-831dr:-:*:*:*:*:*:*:*:

cpe:2.3:o:trendnet:tew-831dr_firmware:1.0_601.130.1.1356:*:*:*:*:*:*:*:

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
@NCCGroupInfosec	Technical Advisory – Multiple Vulnerabilities in Trendnet TEW-831DR WiFi Router (CVE-2022-30325, CVE-2022-30326, CV… twitter.com/i/web/status/1…	2022-06-10 18:36:20
@buaqbot	Technical Advisory – Multiple Vulnerabilities in Trendnet TEW-831DR WiFi Router (CVE-2022-30325, CVE-2022-30326, CV… twitter.com/i/web/status/1…	2022-06-10 19:21:17
@CVEreport	CVE-2022-30326 : An issue was found on TRENDnet TEW-831DR 1.0 601.130.1.1356 devices. The network pre-shared key fi… twitter.com/i/web/status/1…	2022-06-16 23:05:39
@threatmeter	CVE-2022-30326 An issue was found on TRENDnet TEW-831DR 1.0 601.130.1.1356 devices. The network pre-shared key fiel… twitter.com/i/web/status/1…	2022-06-17 07:10:03
@circl_lu	research.nccgroup.com/2022/06/10/tec… Technical Advisory – Multiple Vulnerabilities in Trendnet TEW-831DR WiFi Router (CVE-2022-… twitter.com/i/web/status/1…	2022-06-17 09:18:02
@Har_sia	CVE-2022-30326 har-sia.info/CVE-2022-30326… #HarsiaInfo	2022-06-17 23:02:11
/r/netcve	CVE-2022-30326	2022-06-17 00:38:46

← Previous ID

Next ID→

CVE.report and Source URL Uptime Status status.cve.report