CVE-2022-46531

MITRE | NVD | CVE.ORG | JSON API | Print: PDF

Summary

CVE	CVE-2022-46531
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-12-20 15:15:00 UTC
Updated	2022-12-24 04:20:00 UTC
Description	Tenda F1203 V2.0.1.6 was discovered to contain a buffer overflow via the deviceId parameter at /goform/addWifiMacFilter.

Risk And Classification

Problem Types: CWE-120

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	F1203	-	All	All	All
Operating System	Tenda	F1203 Firmware	2.0.1.6	All	All	All

References

Reference	Source	Link	Tags
CVE-vulns/addWifiMacFilter_deviceId.md at main · Double-q1015/CVE-vulns · GitHub	MISC	github.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status **status.cve.report**