# CVE-2023-39068

MITRE | NVD | CVE.ORG | JSON API | Print: PDF

## Summary

| | |
|---|---|
| **CVE** | CVE-2023-39068 |
| **State** | PUBLIC |
| **Assigner** | cve@mitre.org |
| **Source Priority** | CVE Program / NVD first with legacy fallback |
| **Published** | 2023-09-11 19:15:00 UTC |
| **Updated** | 2023-09-14 17:45:00 UTC |
| **Description** | Buffer Overflow vulnerability in NBD80S09S-KLC v.YK_HZXM_NBD80S09S-KLC_V4.03.R11.7601.Nat.OnvifC.20230414.b |

## Risk And Classification

**Problem Types:** CWE-120

## NVD Known Affected Configurations (CPE 2.3)

| Type | Vendor | Product | Version | Update |
|---|---|---|---|---|
| Hardware | Xiongmaitech | Nb080s09s-klc | - | All |
| Operating System | Xiongmaitech | Nb080s09s-klc Firmware | yk_hzxm_nbd80s09s-klc_v4.03.r11.7601.nat.onvifc.20230414 | All |
| Hardware | Xiongmaitech | Nbd80n32ra-kl-v3 | - | All |
| Operating System | Xiongmaitech | Nbd80n32ra-kl-v3 Firmware | yk_hzxm_nbd80n32ra-kl_v4.03.r11.7601.nat.onvifc.20220120 | All |

## References

| Reference | Source | Link |
|---|---|---|
| Hangzhou Xiongmai Technology Co.,LTD.-Buffer overflow vulnerability exists in Web service firmware of some devices | MISC | www.x |
| CVE Program record | CVE.ORG | www.c |
| NVD vulnerability detail | NVD | nvd.nis |

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.