



CVE-2002-1067

Published on: 08/31/2002 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:01 PM UTC

CVE-2002-1067

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Ic9 Pocket Print Server Firmware](#) from [Seh](#) contain the following vulnerability:

Administrative web interface for IC9 Pocket Print Server Firmware 7.1.30 and 7.1.36f allows remote attackers to cause a denial of service (reboot and reset) via a long password, possibly due to a buffer overflow.

CVE-2002-1067 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **5 - MEDIUM**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

NONE

Integrity
Impact

NONE

Availability
Impact

PARTIAL

CVE References

Description

Tags

Link

ISS X-Force Database: seh-ic9-password-bo (9702): SEH IC9 Pocket Print Server administrative password buffer overflow

[Patch](#)
[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[XF seh-ic9-password-bo\(9702\)](#)

SEH IC9 Pocket Print Server Web Administrative Interface Password Denial Of Service Vulnerability

[Patch](#)
[Vendor Advisory](#)
[cve.report \(archive\)](#)
[text/html](#)

[BID 5329](#)

Neohapsis Archives - Bugtraq - 0815 ++ */ SEH_Web - From kim0_at_phenoelit.de

[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[BUGTRAQ 20020727 0815 ++ */ SEH_Web](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Seh	Ic9 Pocket Print Server Firmware	7.1.30	All	All	All
Hardware 	Seh	Ic9 Pocket Print Server Firmware	7.1.36	All	All	All
Hardware 	Seh	Ic9 Pocket Print Server Firmware	7.1.30	All	All	All
Hardware 	Seh	Ic9 Pocket Print Server Firmware	7.1.36	All	All	All
cpe:2.3:h:seh:ic9_pocket_print_server_firmware:7.1.30:****:****:						
cpe:2.3:h:seh:ic9_pocket_print_server_firmware:7.1.36:****:****:						
cpe:2.3:h:seh:ic9_pocket_print_server_firmware:7.1.30:****:****:						
cpe:2.3:h:seh:ic9_pocket_print_server_firmware:7.1.36:****:****:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)