




CVE-2005-2329

Published on: 07/20/2005 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:28 PM UTC

CVE-2005-2329

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [In Reach Lx 1000s](#) from [Mrv Communications](#) contain the following vulnerability:

MRV Communications In-Reach LX-8000S, LX-4000S, and LX-1000S 3.5.0, when using SSH public key authentication, does not properly restrict access to ports, which allows remote authenticated users to access the consoles of other users.

CVE-2005-2329 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **4.6 - MEDIUM**

**Access
Vector**

LOCAL

**Access
Complexity**

LOW

Authentication

NONE

**Confidentiality
Impact**

PARTIAL

**Integrity
Impact**

PARTIAL

**Availability
Impact**

PARTIAL

CVE References

Description

Tags

Link

SecurityFocus

[Exploit](#)
[Vendor Advisory](#)
www.securityfocus.com
[text/html](#)

[BUGTRAQ 20050718 MRV In-Reach console server: Port Access Control Bypass Vulnerability](#)

SecurityTracker.com Archives - MRV's In-Reach Port-Specific Access Controls Can Be Bypassed By Remote Authenticated Users

[securitytracker.com](#)
[text/html](#)

[SECTRAK 1014517](#)

MRV Communications In-Reach Console Servers Access Control Bypass Vulnerability

[cve.report \(archive\)](#)
[text/html](#)

[BID 14300](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Mrv Communications	In Reach Lx 1000s	3.5	All	All	All
Hardware  	Mrv Communications	In Reach Lx 1000s	3.5	All	All	All
Hardware  	Mrv Communications	In Reach Lx 4000s	3.5	All	All	All
Hardware  	Mrv Communications	In Reach Lx 4000s	3.5	All	All	All
Hardware  	Mrv Communications	In Reach Lx 8000s	3.5	All	All	All
Hardware  	Mrv Communications	In Reach Lx 8000s	3.5	All	All	All
cpe:2.3:h:mrv_communications:in_reach_lx_1000s:3.5:*****:						
cpe:2.3:h:mrv_communications:in_reach_lx_1000s:3.5:*****:						
cpe:2.3:h:mrv_communications:in_reach_lx_4000s:3.5:*****:						
cpe:2.3:h:mrv_communications:in_reach_lx_4000s:3.5:*****:						
cpe:2.3:h:mrv_communications:in_reach_lx_8000s:3.5:*****:						
cpe:2.3:h:mrv_communications:in_reach_lx_8000s:3.5:*****:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)