



CVE-2005-2487

Published on: 08/07/2005 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:27 PM UTC

CVE-2005-2487

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Intrepid 6064 Director Switch](#) from [Mcddata](#) contain the following vulnerability:

Unknown vulnerability in Sun McData switches and directors 4300, 4500, 6064, and 6140 before E/OS 6.0.0 may allow attackers to cause a denial of service (connectivity and array access loss) via a network broadcast storm.

CVE-2005-2487 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **2.1 - LOW**

Access Vector

LOCAL

Access Complexity

LOW

Authentication

NONE

Confidentiality Impact

NONE

Integrity Impact

NONE

Availability Impact

PARTIAL

CVE References

Description

Tags

Link

McDATA E/OS Remote Denial Of Service Vulnerability

[cve.report \(archive\)](#)
[text/html](#)

[🌐 BID 14475](#)

Secunia - Advisories - McDATA Switches / Directors Network Broadcast Storm Denial of Service

[Patch](#)
[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)

[X SECUNIA 16295](#)

#101833: A Network Broadcast Storm May Cause McData Switches and Directors to Lose ISL Connectivity

[Patch](#)
[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[🌐 SUNALERT 101833](#)

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](#)
[text/html](#)

[🔗 XF mcddata-switch-director-dos\(21706\)](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Mcdata	Intrepid 6064 Director Switch	All	All	All	All
Hardware  	Mcdata	Intrepid 6064 Director Switch	All	All	All	All
Hardware  	Mcdata	Intrepid 6140 Director Switch	All	All	All	All
Hardware  	Mcdata	Intrepid 6140 Director Switch	All	All	All	All
Hardware  	Mcdata	Sphereon 4300 Fabric Switch	All	All	All	All
Hardware  	Mcdata	Sphereon 4300 Fabric Switch	All	All	All	All
Hardware  	Mcdata	Sphereon 4500 Fabric Switch	All	All	All	All
Hardware  	Mcdata	Sphereon 4500 Fabric Switch	All	All	All	All

```
cpe:2.3:h:mcddata:intrepid_6064_director_switch:*:*:*:*:*:*:
```

```
cpe:2.3:h:mcddata:intrepid 6064 director switch:*.~*~*~*~*~*~*~*~*~*
```

```
cpe:2.3:h:mcdatalabs:intrepid 6140 director switch.*.*.*.*.*.*.*.*
```

```
cpe:2.3:h:mcddata:intrepid_6140_director_switch:*:*:*:*:*.*.*
```

```
cpe:2.3:h:mcddata:sphereon_4300_fabric_switch:*:*:*:*:*:*:
```

cpe:2.3:h:mcddata:sphereon 4300 fabric switch:*.*.*.*.*.*.*.*

```
cpe:2.3:h:mcddata:sphereon 4500 fabric switch:*:*:*:*:*:*:
```

```
cpe:2.3:h:mcdatalabs:sphereon 4500 fabric switch:*.*.*.*.*.*.*.*
```

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)