



CVE-2005-3715

Published on: 11/21/2005 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:23 PM UTC

CVE-2005-3715

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Si-680h Wireless Voip Phone](#) from [Senao](#) contain the following vulnerability:

Senao SI-680H Wireless VoIP Phone Firmware 0.03.0839 leaves the VxWorks debugger UDP port 17185 available without authentication, which allows attackers to access the phone OS, obtain sensitive information, and cause a denial of service.

CVE-2005-3715 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **7.5 - HIGH**

Access
Vector

Access
Complexity

Authentication

NETWORK

LOW

NONE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

PARTIAL

PARTIAL

PARTIAL

CVE References

Description

Tags

Link

Secunia - Advisories - Senao SI-680H Wireless VoIP Phone Potential Denial of Service

[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)

[X SECUNIA 17606](#)

Senao SI-680H and SI-7800H VOIP WIFI Phones VxWorks Remote Debugger Access Vulnerability

[cve.report \(archive\)](#)
[text/html](#)

[🌐 BID 15475](#)

Webmail : Solution de messagerie professionnelle - OVHcloud-OVH

[www.vupen.com](#)
[text/html](#)

[🌐 VUPEN ADV-2005-2474](#)

[Full-disclosure] Senao SI-680H VoIP Wifi phone undocumented open port

[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)

[Inactive Link](#) [Not Archived](#)

[🌐 FULLDISC 20051116 Senao SI-680H VoIP Wifi phone undocumented open port](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that

... or interest to your interest, ensure to examine content of other sites being referenced, or not, from this page. There may be other resources that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Senao	Si-680h Wireless Voip Phone	1.7.0_firmware_0.03.0839	All	All	All
Hardware 	Senao	Si-680h Wireless Voip Phone	1.7.0_firmware_0.03.0839	All	All	All
cpe:2.3:h:senao:si-680h_wireless_voip_phone:1.7.0_firmware_0.03.0839:*****:						
cpe:2.3:h:senao:si-680h_wireless_voip_phone:1.7.0_firmware_0.03.0839:*****:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)

© [CVE.report](#) 2023   |
Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)