




CVE-2005-3718

Published on: 11/21/2005 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:22 PM UTC

CVE-2005-3718

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of **F1000 Voip Wifi Phone** from **Utstarcom** contain the following vulnerability:

UTStarcom F1000 VOIP WIFI Phone s2.0 running VxWorks 5.5.1 with kernel WIND 2.6 does not allow users to disable access to (1) SNMP or (2) the rlogin port TCP 513, which allows remote attackers to exploit other vulnerabilities such as CVE-2005-3716, or execute arbitrary shell commands via rlogin, which does not require authentication.

CVE-2005-3718 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **7.5 - HIGH**

**Access
Vector**

NETWORK

**Access
Complexity**

LOW

Authentication

NONE

**Confidentiality
Impact**

PARTIAL

**Integrity
Impact**

PARTIAL

**Availability
Impact**

PARTIAL

CVE References

Description

Tags

Link

Secunia - Advisories - UTStarcom F1000 Wi-Fi Handset Multiple Vulnerabilities

[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)

[X](#) [SECUNIA 17629](#)

UTStarcom F1000 VOIP WIFI Phone Multiple Remote Access Vulnerabilities

[cve.report \(archive\)](#)
[text/html](#)

[🌐](#) [BID 15476](#)

[Full-disclosure] UTstarcom F1000 VoIP Wifi phone multiple vulnerabilities

[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[🌐](#) [FULLDISC 20051117 UTstarcom F1000 VoIP Wifi phone multiple vulnerabilities](#)

Webmail - OVH

[www.vupen.com](#)
[text/html](#)

[🌐](#) [VUPEN ADV-2005-2472](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Utstarcom	F1000 Voip Wifi Phone	2.0	All	All	All
Hardware 	Utstarcom	F1000 Voip Wifi Phone	2.0	All	All	All
cpe:2.3:h:utstarcom:f1000_voip_wifi_phone:2.0:*****:.*:						
cpe:2.3:h:utstarcom:f1000_voip_wifi_phone:2.0:*****:.*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)