




CVE-2005-3804

Published on: 11/24/2005 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:22 PM UTC

CVE-2005-3804

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [7920 Wireless Ip Phone](#) from [Cisco](#) contain the following vulnerability:

Cisco IP Phone (VoIP) 7920 1.0(8) listens to UDP port 17185 to support a VxWorks debugger, which allows remote attackers to obtain sensitive information and cause a denial of service.

CVE-2005-3804 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **6.4 - MEDIUM**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

PARTIAL

Integrity
Impact

NONE

Availability
Impact

PARTIAL

CVE References

Description

Tags

Link

Cisco 7920 Wireless IP Phone VxWorks Remote Debugger Access Vulnerability

[cve.report \(archive\)](#)
[text/html](#)

[🌐](#) [BID 15456](#)

Secunia - Advisories - Cisco Wireless IP Phone Two Vulnerabilities

[Patch](#)
[Vendor Advisory](#)
[web.archive.org](#)
[text/html](#)

[X](#) [SECUNIA 17604](#)

Cisco - Networking, Cloud, and Cybersecurity Solutions

[Patch](#)
[Vendor Advisory](#)
[www.cisco.com](#)
[text/html](#)

[🌐](#) [CISCO 20051116 Fixed SNMP Communities and Open UDP Port in Cisco 7920 Wireless IP Phone](#)

SecurityTracker.com Archives - Cisco 7920 Wireless IP Phone Grants Remote Users SNMP Access, Discloses Debugging Information, and Lets Remote Users Deny Service

[Vendor Advisory](#)
[securitytracker.com](#)
[text/html](#)

[🌐](#) [SECTrack 1015232](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Cisco	7920 Wireless Ip Phone	1.0(8)	All	All	All
Hardware  	Cisco	7920 Wireless Ip Phone	1.0(8\)	All	All	All
Hardware  	Cisco	7920 Wireless Ip Phone	2.0	All	All	All
Hardware  	Cisco	7920 Wireless Ip Phone	1.0(8\)	All	All	All
Hardware  	Cisco	7920 Wireless Ip Phone	2.0	All	All	All
cpe:2.3:h:cisco:7920_wireless_ip_phone:1.0(8):*:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:h:cisco:7920_wireless_ip_phone:1.0(8\):*:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:h:cisco:7920_wireless_ip_phone:2.0:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:h:cisco:7920_wireless_ip_phone:1.0(8\):*:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:h:cisco:7920_wireless_ip_phone:2.0:~::~~::~~::~~::~~::~~::~~:::						

No vendor comments have been submitted for this CVE

← Previous ID

Next ID →