



CVE-2012-3012

Published on: 09/05/2012 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:17 PM UTC

CVE-2012-3012

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of **Power Sentinel** from **Arbiter** contain the following vulnerability:

The Arbiter Power Sentinel 1133A device with firmware before 11Jun2012 Rev 421 allows remote attackers to cause a denial of service (Ethernet outage) via unspecified Ethernet traffic that fills a buffer, as demonstrated by a port scan.

CVE-2012-3012 has been assigned by ics-cert@hq.dhs.gov to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

NONE

Integrity
Impact

NONE

Availability
Impact

COMPLETE

CVE References

Description

Tags

Link

404 - File Not Found | CISA

[US Government Resource](#)

[www.us-cert.gov](#)

[application/pdf](#)

[Inactive Link](#) [Not Archived](#)

MISC [www.us-cert.gov/control_systems/pdf/ICSA-12-249-01.pdf](#)

News in Precision Timing and Power Measurement Industry

[www.arbiter.com](#)

[text/html](#)

CONFIRM [www.arbiter.com/news/index.php?id=261](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Arbiter	Power Sentinel	1133a	All	All	All
Hardware 	Arbiter	Power Sentinel	1133a	All	All	All
Operating System	Arbiter	Power Sentinel 1133a Firmware	All	All	All	All
cpe:2.3:h:arbiter:power_sentinel:1133a:*****:						
cpe:2.3:h:arbiter:power_sentinel:1133a:*****:						
cpe:2.3:o:arbiter:power_sentinel_1133a_firmware:*****:						
No vendor comments have been submitted for this CVE						
← Previous ID			Next ID →			