




CVE-2012-4089

Published on: 09/24/2013 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:15 PM UTC

CVE-2012-4089

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Unified Computing System](#) from [Cisco](#) contain the following vulnerability:

MCTOOLS in the fabric interconnect in Cisco Unified Computing System (UCS) allows local users to execute arbitrary Baseboard Management Controller (BMC) commands by leveraging (1) local, (2) shell-level, or (3) debug-level privileges at the operating-system layer, aka Bug ID CSCtg76239.

CVE-2012-4089 has been assigned by [psirt@cisco.com](#) to track the vulnerability

CVSS2 Score: **6.6 - MEDIUM**

Access Vector

LOCAL

Access Complexity

MEDIUM

Authentication

SINGLE

Confidentiality Impact

COMPLETE

Integrity Impact

COMPLETE

Availability Impact

COMPLETE

CVE References

Description

Tags

Link

Cisco Unified Computing System MCTools Command Injection Flaw Lets Local Users Gain Elevated Privileges - SecurityTracker

[Third Party Advisory](#)
[VDB Entry](#)
[www.securitytracker.com](#)
[text/html](#)

[SECTrack 1029082](#)

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](#)
[text/html](#)

[XF cisco-ucs-cve20124089-command-exec\(87369\)](#)

Cisco Security Notice: Cisco Unified Computing System Baseboard Management Controller Arbitrary Command Execution Vulnerability

[Vendor Advisory](#)
[tools.cisco.com](#)
[text/html](#)

[CISCO 20130923 Cisco Unified Computing System Baseboard Management Controller Arbitrary Command Execution Vulnerability](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that

are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Cisco	Unified Computing System	-	All	All	All
Hardware  	Cisco	Unified Computing System	-	All	All	All
<pre>cpe:2.3:h:cisco:unified_computing_system:-:*.***.***.***</pre>						
<pre>cpe:2.3:h:cisco:unified_computing_system:-:*.***.***.***</pre>						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report