




Last Modified on: 03/23/2021 11:28:22 PM UTC

CVE-2012-6276

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF 

Certain versions of **TL-wr841n** from **Tp-link** contain the following vulnerability:

Directory traversal vulnerability in the web-based management interface on the TP-LINK TL-WR841N router with firmware 3.13.9 build 120201 Rel.54965n and earlier allows remote attackers to read arbitrary files via the URL parameter.

CVE-2012-6276 has been assigned by  cert@cert.org to track the vulnerability

CVSS2 Score: 4.3 - MEDIUM

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
Vulnerability Note VU#185100 - TP-LINK TL-WR841N wireless router local file inclusion vulnerability	US Government Resource www.kb.cert.org text/html	 CERT-VN VU#185100

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tp-link	Tl-wr841n	-	All	All	All
Hardware 	Tp-link	Tl-wr841n	-	All	All	All
Operating System	Tp-link	Tl-wr841n Firmware	3.13.9	All	All	All
Operating System	Tp-link	Tl-wr841n Firmware	3.13.9	All	All	All
cpe:2.3:h:tp-link:tl-wr841n:-:*****:						
cpe:2.3:h:tp-link:tl-wr841n:-:*****:						
cpe:2.3:o:tp-link:tl-wr841n_firmware:3.13.9:*****:						
cpe:2.3:o:tp-link:tl-wr841n_firmware:3.13.9:*****:						
No vendor comments have been submitted for this CVE						
← Previous ID Next ID→						