



CVE-2013-2578

Published on: 10/11/2013 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:43 PM UTC


CVE-2013-2578

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Lm Firmware](#) from [Tp-link](#) contain the following vulnerability:

cgi-bin/admin/servlettest in TP-Link IP Cameras TL-SC3130, TL-SC3130G, TL-SC3171, TL-SC3171G, and possibly other models before beta firmware LM.1.6.18P12_sign6 allows remote attackers to execute arbitrary commands via shell metacharacters in (1) the ServerName parameter and (2) other unspecified parameters.

CVE-2013-2578 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **10 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

COMPLETE

Integrity
Impact

COMPLETE

Availability
Impact

COMPLETE

CVE References

Description

Tags

Link

Multiple Vulnerabilities in TP-Link TL-SC3171 IP Cameras | CORE Security

[Exploit](#)

[www.coresecurity.com](#)

[text/html](#)

[MISC](#) www.coresecurity.com/advisories/multiple-vulnerabilities-tp-link-tl-sc3171-ip-cameras

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Tp-link	Lm Firmware	All	All	All	All
Hardware 	Tp-link	Tl-sc3130	-	All	All	All
Hardware 	Tp-link	Tl-sc3130	-	All	All	All
Hardware 	Tp-link	Tl-sc3130g	-	All	All	All
Hardware 	Tp-link	Tl-sc3130g	-	All	All	All
Hardware 	Tp-link	Tl-sc3171	-	All	All	All
Hardware 	Tp-link	Tl-sc3171	-	All	All	All
Hardware 	Tp-link	Tl-sc3171g	-	All	All	All
Hardware 	Tp-link	Tl-sc3171g	-	All	All	All
cpe:2.3:o:tp-link:lm_firmware:*****:						
cpe:2.3:h:tp-link:tl-sc3130:-:*****:						
cpe:2.3:h:tp-link:tl-sc3130:-:*****:						
cpe:2.3:h:tp-link:tl-sc3130g:-:*****:						
cpe:2.3:h:tp-link:tl-sc3130g:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171g:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171g:-:*****:						
No vendor comments have been submitted for this CVE						
← Previous ID				Next ID →		