




CVE-2013-2581

Published on: 10/11/2013 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:42 PM UTC

CVE-2013-2581

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Lm Firmware](#) from [Tp-link](#) contain the following vulnerability:

cgi-bin/firmwareupgrade in TP-Link IP Cameras TL-SC3130, TL-SC3130G, TL-SC3171, TL-SC3171G, and possibly other models before beta firmware LM.1.6.18P12_sign6 allows remote attackers to modify the firmware revision via a "preset" action.

CVE-2013-2581 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

NONE

Integrity
Impact

COMPLETE

Availability
Impact

NONE

CVE References

Description

Tags

Link

About Secunia Research | Flexera

[Vendor Advisory](#)
[secunia.com](#)
[Deprecated Link](#)
[text/plain](#)

[X SECUNIA 54155](#)

Multiple Vulnerabilities in TP-Link TL-SC3171 IP
Cameras | CORE Security

[Exploit](#)
[www.coresecurity.com](#)
[text/html](#)

[MISC www.coresecurity.com/advisories/multiple-vulnerabilities-tp-link-tl-sc3171-ip-cameras](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Tp-link	Lm Firmware	All	All	All	All
Hardware  	Tp-link	TL-sc3130	-	All	All	All
Hardware  	Tp-link	TL-sc3130	-	All	All	All
Hardware  	Tp-link	TL-sc3130g	-	All	All	All
Hardware  	Tp-link	TL-sc3130g	-	All	All	All
Hardware  	Tp-link	TL-sc3171	-	All	All	All
Hardware  	Tp-link	TL-sc3171	-	All	All	All
Hardware  	Tp-link	TL-sc3171g	-	All	All	All
Hardware  	Tp-link	TL-sc3171g	-	All	All	All
cpe:2.3:o:tp-link:lm_firmware:*****:						
cpe:2.3:h:tp-link:tl-sc3130:-:*****:						
cpe:2.3:h:tp-link:tl-sc3130:-:*****:						
cpe:2.3:h:tp-link:tl-sc3130g:-:*****:						
cpe:2.3:h:tp-link:tl-sc3130g:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171g:-:*****:						
cpe:2.3:h:tp-link:tl-sc3171g:-:*****:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)

