




CVE-2013-3606

Published on: 01/19/2014 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:31 PM UTC

CVE-2013-3606

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Powerconnect 3348](#) from [Dell](#) contain the following vulnerability:

The login page in the GoAhead web server on Dell PowerConnect 3348 1.2.1.3, 3524p 2.0.0.48, and 5324 2.0.1.4 switches allows remote attackers to cause a denial of service (device outage) via a long username.

CVE-2013-3606 has been assigned by cert@cert.org to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

NONE

Integrity
Impact

NONE

Availability
Impact

COMPLETE

CVE References

Description

Tags

Link

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](https://exchange.xforce.ibmcloud.com/text/html)
text/html

[XF goahead-cve20133606-dos\(90598\)](#)

Vulnerability Note VU#122582 - Dell PowerConnect 3348, 3524p, and 5324 switches are vulnerable to denial-of-service attacks

[Third Party Advisory](#)
[US Government Resource](#)
www.kb.cert.org
text/html

[CERT-VN VU#122582](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Dell	Powerconnect 3348	1.2.1.3	All	All	All
Hardware 	Dell	Powerconnect 3348	1.2.1.3	All	All	All
Hardware 	Dell	Powerconnect 3524p	2.0.0.48	All	All	All
Hardware 	Dell	Powerconnect 3524p	2.0.0.48	All	All	All
Hardware 	Dell	Powerconnect 5324	2.0.1.4	All	All	All
Hardware 	Dell	Powerconnect 5324	2.0.1.4	All	All	All
cpe:2.3:h:dell:powerconnect_3348:1.2.1.3:*****:						
cpe:2.3:h:dell:powerconnect_3348:1.2.1.3:*****:						
cpe:2.3:h:dell:powerconnect_3524p:2.0.0.48:*****:						
cpe:2.3:h:dell:powerconnect_3524p:2.0.0.48:*****:						
cpe:2.3:h:dell:powerconnect_5324:2.0.1.4:*****:						
cpe:2.3:h:dell:powerconnect_5324:2.0.1.4:*****:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)