



CVE-2013-5038

Published on: 12/29/2013 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:36 PM UTC


CVE-2013-5038

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Hotbox Router](#) from [Hot](#) contain the following vulnerability:

The HOT HOTBOX router with software 2.1.11 allows remote attackers to bypass authentication by configuring a source IP address that had previously been used for an authenticated session.

CVE-2013-5038 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **5.8 - MEDIUM**

Access
Vector

Access
Complexity

Authentication

ADJACENT_NETWORK

LOW

NONE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

PARTIAL

PARTIAL

PARTIAL

CVE References

Description

Tags

Link

HOTBOX 2.1.11 CSRF / Traversal / Denial Of Service ≈ Packet Storm

Exploit
packetstormsecurity.com
text/html

MISC packetstormsecurity.com/files/123901/HOTBOX-2.1.11-CSRF-Traversal-Denial-Of-Service.html

HOTBOX Multiple Vulnerabilities - YouTube

Exploit
www.youtube.com
text/html

MISC www.youtube.com/watch?v=CPIT09Zlj48

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Hot	Hotbox Router	-	All	All	All
Hardware 	Hot	Hotbox Router	-	All	All	All
Operating System	Hot	Hotbox Router Firmware	2.1.11	All	All	All
Operating System	Hot	Hotbox Router Firmware	2.1.11	All	All	All
cpe:2.3:h:hot:hotbox_router:-:*****:						
cpe:2.3:h:hot:hotbox_router:-:*****:						
cpe:2.3:o:hot:hotbox_router_firmware:2.1.11:*****:						
cpe:2.3:o:hot:hotbox_router_firmware:2.1.11:*****:						
No vendor comments have been submitted for this CVE						
← Previous ID				Next ID →		