



CVE-2013-6684

Published on: 11/13/2013 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:38 PM UTC


CVE-2013-6684

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Wireless Lan Controller](#) from [Cisco](#) contain the following vulnerability:

The web framework on Cisco Wireless LAN Controller (WLC) devices does not properly validate configuration parameters, which allows remote authenticated users to cause a denial of service via a crafted HTTP request, aka Bug ID CSCuh81011.

CVE-2013-6684 has been assigned by [cisco](#) psirt@cisco.com to track the vulnerability

CVSS2 Score: **6.8 - MEDIUM**

Access Vector

Access Complexity

Authentication

NETWORK

LOW

SINGLE

Confidentiality Impact

Integrity Impact

Availability Impact

NONE

NONE

COMPLETE

CVE References

Description

Tags

Link

Cisco Security Notice: Cisco Wireless LAN Controller HTTP Request Denial of Service Vulnerability

[Vendor Advisory](#)
[tools.cisco.com](#)
[text/html](#)

[CISCO 20131112 Cisco Wireless LAN Controller HTTP Request Denial of Service Vulnerability](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Cisco	Wireless Lan Controller	All	All	All	All
Hardware 	Cisco	Wireless Lan Controller	All	All	All	All
cpe:2.3:h:cisco:wireless_lan_controller:*****:						
cpe:2.3:h:cisco:wireless_lan_controller:*****:						
No vendor comments have been submitted for this CVE						
← Previous ID			Next ID →			