



CVE-2013-6698

Published on: 11/22/2013 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:37 PM UTC


CVE-2013-6698

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Wireless Lan Controller](#) from [Cisco](#) contain the following vulnerability:

The web interface on Cisco Wireless LAN Controller (WLC) devices does not properly restrict use of IFRAME elements, which makes it easier for remote attackers to conduct clickjacking attacks and unspecified other attacks via a crafted web site, related to a "cross-frame scripting (XFS)" issue, aka Bug ID CSCuf77821.

CVE-2013-6698 has been assigned by [psirt@cisco.com](#) to track the vulnerability

CVSS2 Score: **4.3 - MEDIUM**

Access Vector

Access Complexity

Authentication

NETWORK

MEDIUM

NONE

Confidentiality Impact

Integrity Impact

Availability Impact

NONE

PARTIAL

NONE

CVE References

Description

Tags

Link

No Description Provided

[Vendor Advisory](#)
[tools.cisco.com](#)
[text/html](#)

[CISCO 20131121 Cisco Wireless LAN Controller Cross-Frame Scripting Vulnerability](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Cisco	Wireless Lan Controller	All	All	All	All
Hardware 	Cisco	Wireless Lan Controller	All	All	All	All
cpe:2.3:h:cisco:wireless_lan_controller:*****:						
cpe:2.3:h:cisco:wireless_lan_controller:*****:						
No vendor comments have been submitted for this CVE						
← Previous ID			Next ID →			