



CVE-2014-9194

Published on: 01/16/2015 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:25:59 PM UTC

CVE-2014-9194

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [1094b Gps Substation Clock](#) from [Arbiter](#) contain the following vulnerability:

Arbiter 1094B GPS Substation Clock allows remote attackers to cause a denial of service (disruption) via crafted radio transmissions that spoof GPS satellite broadcasts.

CVE-2014-9194 has been assigned by ics-cert@hq.dhs.gov to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

NONE

Integrity
Impact

NONE

Availability
Impact

COMPLETE

CVE References

Description

Tags

Link

Arbiter Systems 1094B GPS Clock Spoofing Vulnerability | ICS-CERT

[Third Party Advisory](#)[US Government Resource](#)ics-cert.us-cert.gov[text/html](#)

[MISC ics-cert.us-cert.gov/advisories/ICSA-14-345-01](https://ics-cert.us-cert.gov/advisories/ICSA-14-345-01)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Known/Affected Configurations (CPE V2.0)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Arbiter	1094b Gps Substation Clock	-	All	All	All
Hardware	Arbiter	1094b Gps Substation Clock	-	All	All	All
cpe:2.3:h:arbiter:1094b_gps_substation_clock:-:*****:.*:						
cpe:2.3:h:arbiter:1094b_gps_substation_clock:-:*****:.*:						
No vendor comments have been submitted for this CVE						
← Previous ID			Next ID →			