



CVE-2015-2867

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2015-2867
State	PUBLIC
Assigner	cert@cert.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2017-01-06 21:59:00 UTC
Updated	2017-01-11 02:59:00 UTC
Description	A design flaw in the Trane ComfortLink II SCC firmware version 2.0.2 service allows remote attackers to take complete con

Risk And Classification

Problem Types: CWE-798

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Trane	Comfortlink li Firmware	2.0.2	All	All	All
Operating System	Trane	Comfortlink li Firmware	2.0.2	All	All	All

References

Reference	Source	Link
TRANE COMFORTLINK II CVE-2015-2867 Hardcoded Credentials Security Bypass Vulnerability	BID	www.securityfocus.com
Cisco Talos - Talos 2016 0028	MISC	www.talosintelligence.com
CVE Program record	CVE.ORG	www.cve.org
NVD vulnerability detail	NVD	nvd.nist.gov

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)