



Published on: 11/18/2015 12:00:00 AM UTC


Last Modified on: 03/23/2021 11:26:17 PM UTC

CVE-2015-6369

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF 

Certain versions of **Firepower Extensible Operating System** from **Cisco** contain the following vulnerability:

The USB driver in Cisco Firepower Extensible Operating System 1.1(1.160) on Firepower 9000 devices allows physically proximate attackers to cause a denial of service via a crafted USB device that triggers invalid USB commands, aka Bug ID CSCux10531.

CVE-2015-6369 has been assigned by psirt@cisco.com to track the vulnerability

CVSS2 Score: 4.9 - MEDIUM

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	COMPLETE

CVE References

Description	Tags	Link
Cisco Firepower 9000 USB Kernel Denial of Service Vulnerability	Vendor Advisory tools.cisco.com text/html	 CISCO 20151117 Cisco Firepower 9000 USB Kernel Denial of Service Vulnerability

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Cisco	Firepower Extensible Operating System	1.1(1.160)	All	All	All
Operating System	Cisco	Firepower Extensible Operating System	1.1\1(1.160\)	All	All	All
Operating System	Cisco	Firepower Extensible Operating System	1.1\1(1.160\)	All	All	All
cpe:2.3:o:cisco:firepower_extensible_operating_system:1.1(1.160):*:~::~:						
cpe:2.3:o:cisco:firepower_extensible_operating_system:1.1\1(1.160\):*:~::~:						
cpe:2.3:o:cisco:firepower_extensible_operating_system:1.1\1(1.160\):*:~::~:						
No vendor comments have been submitted for this CVE						
← Previous ID			Next ID →			