




CVE-2017-14515

Published on: 09/17/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:45 PM UTC

CVE-2017-14515

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [W15e](#) from [Tenda](#) contain the following vulnerability:

Heap-based Buffer Overflow on Tenda W15E devices before 15.11.0.14 allows remote attackers to cause a denial of service (temporary HTTP outage and forced logout) via unspecified vectors.

CVE-2017-14515 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **5 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	PARTIAL

CVE References

Description	Tags	Link
Overview-Tenda-All For Better NetWorking	Vendor Advisory www.tendacn.com text/html	CONFIRM www.tendacn.com/en/2018.html

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tenda	W15e	-	All	All	All
Hardware 	Tenda	W15e	-	All	All	All
Operating System	Tenda	W15e Firmware	All	All	All	All
cpe:2.3:h:tenda:w15e:-:*:*:*:*:*:						
cpe:2.3:h:tenda:w15e:-:*:*:*:*:*:						
cpe:2.3:o:tenda:w15e_firmware:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)