




CVE-2017-15629

Published on: 01/11/2018 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:33 PM UTC

CVE-2017-15629

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Er5110g](#) from [Tp-link](#) contain the following vulnerability:

TP-Link WVR, WAR and ER devices allow remote authenticated administrators to execute arbitrary commands via command injection in the new-tunnelname variable in the pptp_client.lua file.

CVE-2017-15629 has been assigned by [M](#) [cve@mitre.org](#) to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.2 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	HIGH	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **9 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Vulnerability/CVE-2017-15613_to_CVE-2017-15637.txt at master · chunibalon/Vulnerability · GitHub	Exploit Third Party Advisory github.com text/html	MISC github.com/chunibalon/Vulnerability/blob/master/CVE-2017-15613_to_CVE-2017-15637.txt

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tp-link	Er5110g	-	All	All	All
Hardware 	Tp-link	Er5110g	-	All	All	All
Operating System	Tp-link	Er5110g Firmware	-	All	All	All
Operating System	Tp-link	Er5110g Firmware	-	All	All	All
Hardware 	Tp-link	Er5120g	-	All	All	All
Hardware 	Tp-link	Er5120g	-	All	All	All
Operating System	Tp-link	Er5120g Firmware	-	All	All	All
Operating System	Tp-link	Er5120g Firmware	-	All	All	All
Hardware 	Tp-link	Er5510g	-	All	All	All
Hardware 	Tp-link	Er5510g	-	All	All	All
Operating System	Tp-link	Er5510g Firmware	-	All	All	All
Operating System	Tp-link	Er5510g Firmware	-	All	All	All
Hardware 	Tp-link	Er5520g	-	All	All	All
Hardware 	Tp-link	Er5520g	-	All	All	All
Operating System	Tp-link	Er5520g Firmware	-	All	All	All
Operating System	Tp-link	Er5520g Firmware	-	All	All	All
Hardware 	Tp-link	R4149g	-	All	All	All
Hardware 	Tp-link	R4149g	-	All	All	All
Operating System	Tp-link	R4149g Firmware	-	All	All	All

System						
Operating System	Tp-link	R4149g Firmware	-	All	All	All
Hardware  	Tp-link	R4239g	-	All	All	All
Hardware  	Tp-link	R4239g	-	All	All	All
Operating System	Tp-link	R4239g Firmware	-	All	All	All
Operating System	Tp-link	R4239g Firmware	-	All	All	All
Hardware  	Tp-link	R4299g	-	All	All	All
Hardware  	Tp-link	R4299g	-	All	All	All
Operating System	Tp-link	R4299g Firmware	-	All	All	All
Operating System	Tp-link	R4299g Firmware	-	All	All	All
Hardware  	Tp-link	R473	-	All	All	All
Hardware  	Tp-link	R473	-	All	All	All
Hardware  	Tp-link	R473g	-	All	All	All
Hardware  	Tp-link	R473g	-	All	All	All
Hardware  	Tp-link	R473gp-ac	-	All	All	All
Hardware  	Tp-link	R473gp-ac	-	All	All	All
Operating System	Tp-link	R473gp-ac Firmware	-	All	All	All
Operating System	Tp-link	R473gp-ac Firmware	-	All	All	All
Operating System	Tp-link	R473g Firmware	-	All	All	All
Operating System	Tp-link	R473g Firmware	-	All	All	All
Hardware  	Tp-link	R473p-ac	-	All	All	All
Hardware  	Tp-link	R473p-ac	-	All	All	All
Operating System	Tp-link	R473p-ac Firmware	-	All	All	All
Operating System	Tp-link	R473p-ac Firmware	-	All	All	All
Operating System	Tp-link	R473 Firmware	-	All	All	All
Operating System	Tp-link	R473 Firmware	-	All	All	All
Hardware  	Tp-link	R478	-	All	All	All

Hardware 	Tp-link	R478	-	All	All	All
Hardware 	Tp-link	R478	-	All	All	All
Operating System	Tp-link	R478 Firmware	-	All	All	All
Hardware 	Tp-link	R478g	-	All	All	All
Operating System	Tp-link	R478g Firmware	-	All	All	All
Hardware 	Tp-link	R478g	-	All	All	All
Hardware 	Tp-link	R478g	-	All	All	All
Operating System	Tp-link	R478g Firmware	-	All	All	All
Operating System	Tp-link	R478g Firmware	-	All	All	All
Hardware 	Tp-link	R478	-	All	All	All
Hardware 	Tp-link	R478	-	All	All	All
Operating System	Tp-link	R478 Firmware	-	All	All	All
Operating System	Tp-link	R478 Firmware	-	All	All	All
Operating System	Tp-link	R478 Firmware	-	All	All	All
Operating System	Tp-link	R478 Firmware	-	All	All	All
Hardware 	Tp-link	R483	-	All	All	All
Hardware 	Tp-link	R483	-	All	All	All
Hardware 	Tp-link	R483g	-	All	All	All
Hardware 	Tp-link	R483g	-	All	All	All
Operating System	Tp-link	R483g Firmware	-	All	All	All
Operating System	Tp-link	R483g Firmware	-	All	All	All
Operating System	Tp-link	R483 Firmware	-	All	All	All
Operating System	Tp-link	R483 Firmware	-	All	All	All
Hardware 	Tp-link	R488	-	All	All	All
Hardware 	Tp-link	R488	-	All	All	All
Operating System	Tp-link	R488 Firmware	-	All	All	All
Operating	Tp-link	R488 Firmware	-	All	All	All

Operating System	Operating System	Firmware	Operating System	Operating System	Operating System	Operating System
Hardware  	Tp-link	War1300l	-	All	All	All
Hardware  	Tp-link	War1300l	-	All	All	All
Operating System	Tp-link	War1300l Firmware	-	All	All	All
Operating System	Tp-link	War1300l Firmware	-	All	All	All
Hardware  	Tp-link	War1750l	-	All	All	All
Hardware  	Tp-link	War1750l	-	All	All	All
Operating System	Tp-link	War1750l Firmware	-	All	All	All
Operating System	Tp-link	War1750l Firmware	-	All	All	All
Hardware  	Tp-link	War2600l	-	All	All	All
Hardware  	Tp-link	War2600l	-	All	All	All
Operating System	Tp-link	War2600l Firmware	-	All	All	All
Operating System	Tp-link	War2600l Firmware	-	All	All	All
Hardware  	Tp-link	War302	-	All	All	All
Hardware  	Tp-link	War302	-	All	All	All
Operating System	Tp-link	War302 Firmware	-	All	All	All
Operating System	Tp-link	War302 Firmware	-	All	All	All
Hardware  	Tp-link	War450	-	All	All	All
Hardware  	Tp-link	War450	-	All	All	All
Hardware  	Tp-link	War450l	-	All	All	All
Hardware  	Tp-link	War450l	-	All	All	All
Operating System	Tp-link	War450l Firmware	-	All	All	All
Operating System	Tp-link	War450l Firmware	-	All	All	All
Operating System	Tp-link	War450 Firmware	-	All	All	All
Operating System	Tp-link	War450 Firmware	-	All	All	All
Hardware  	Tp-link	War458	-	All	All	All
Hardware  	Tp-link	War458	-	All	All	All

Hardware 	Tp-link	War458l	-	All	All	All
Hardware 	Tp-link	War458l	-	All	All	All
Operating System	Tp-link	War458l Firmware	-	All	All	All
Operating System	Tp-link	War458l Firmware	-	All	All	All
Operating System	Tp-link	War458 Firmware	-	All	All	All
Operating System	Tp-link	War458 Firmware	-	All	All	All
Hardware 	Tp-link	War900l	-	All	All	All
Hardware 	Tp-link	War900l	-	All	All	All
Operating System	Tp-link	War900l Firmware	-	All	All	All
Operating System	Tp-link	War900l Firmware	-	All	All	All
Hardware 	Tp-link	Wvr1300g	-	All	All	All
Hardware 	Tp-link	Wvr1300g	-	All	All	All
Operating System	Tp-link	Wvr1300g Firmware	-	All	All	All
Operating System	Tp-link	Wvr1300g Firmware	-	All	All	All
Hardware 	Tp-link	Wvr1300l	-	All	All	All
Hardware 	Tp-link	Wvr1300l	-	All	All	All
Operating System	Tp-link	Wvr1300l Firmware	-	All	All	All
Operating System	Tp-link	Wvr1300l Firmware	-	All	All	All
Hardware 	Tp-link	Wvr1750l	-	All	All	All
Hardware 	Tp-link	Wvr1750l	-	All	All	All
Operating System	Tp-link	Wvr1750l Firmware	-	All	All	All
Operating System	Tp-link	Wvr1750l Firmware	-	All	All	All
Hardware 	Tp-link	Wvr2600l	-	All	All	All
Hardware 	Tp-link	Wvr2600l	-	All	All	All
Operating System	Tp-link	Wvr2600l Firmware	-	All	All	All
Operating System	Tp-link	Wvr2600l Firmware	-	All	All	All

Hardware  	Tp-link	Wvr300	-	All	All	All
Hardware  	Tp-link	Wvr300	-	All	All	All
Operating System	Tp-link	Wvr300 Firmware	-	All	All	All
Operating System	Tp-link	Wvr300 Firmware	-	All	All	All
Hardware  	Tp-link	Wvr302	-	All	All	All
Hardware  	Tp-link	Wvr302	-	All	All	All
Operating System	Tp-link	Wvr302 Firmware	-	All	All	All
Operating System	Tp-link	Wvr302 Firmware	-	All	All	All
Hardware  	Tp-link	Wvr4300l	-	All	All	All
Hardware  	Tp-link	Wvr4300l	-	All	All	All
Operating System	Tp-link	Wvr4300l Firmware	-	All	All	All
Operating System	Tp-link	Wvr4300l Firmware	-	All	All	All
Hardware  	Tp-link	Wvr450	-	All	All	All
Hardware  	Tp-link	Wvr450	-	All	All	All
Hardware  	Tp-link	Wvr450l	-	All	All	All
Hardware  	Tp-link	Wvr450l	-	All	All	All
Operating System	Tp-link	Wvr450l Firmware	1.0161125	All	All	All
Operating System	Tp-link	Wvr450l Firmware	1.0161125	All	All	All
Operating System	Tp-link	Wvr450 Firmware	-	All	All	All
Operating System	Tp-link	Wvr450 Firmware	-	All	All	All
Hardware  	Tp-link	Wvr458l	-	All	All	All
Hardware  	Tp-link	Wvr458l	-	All	All	All
Operating System	Tp-link	Wvr458l Firmware	-	All	All	All
Operating System	Tp-link	Wvr458l Firmware	-	All	All	All
Hardware  	Tp-link	Wvr900g	-	All	All	All
Hardware  	Tp-link	Wvr900g	-	All	All	All
Operating System	Tp-link	Wvr900g Firmware	3.0_170306	All	All	All

Operating System	Tp-link	Wvr900g Firmware	3.0_170306	All	All	All
Hardware	Tp-link	Wvr900l	-	All	All	All
Hardware	Tp-link	Wvr900l	-	All	All	All
Operating System	Tp-link	Wvr900l Firmware	-	All	All	All
Operating System	Tp-link	Wvr900l Firmware	-	All	All	All
cpe:2.3:h:tp-link:er5110g:-:*~::~:						
cpe:2.3:h:tp-link:er5110g:-:*~::~:						
cpe:2.3:o:tp-link:er5110g_firmware:-:*~::~:						
cpe:2.3:o:tp-link:er5110g_firmware:-:*~::~:						
cpe:2.3:h:tp-link:er5120g:-:*~::~:						
cpe:2.3:h:tp-link:er5120g:-:*~::~:						
cpe:2.3:o:tp-link:er5120g_firmware:-:*~::~:						
cpe:2.3:o:tp-link:er5120g_firmware:-:*~::~:						
cpe:2.3:h:tp-link:er5510g:-:*~::~:						
cpe:2.3:h:tp-link:er5510g:-:*~::~:						
cpe:2.3:o:tp-link:er5510g_firmware:-:*~::~:						
cpe:2.3:o:tp-link:er5510g_firmware:-:*~::~:						
cpe:2.3:h:tp-link:er5520g:-:*~::~:						
cpe:2.3:h:tp-link:er5520g:-:*~::~:						
cpe:2.3:o:tp-link:er5520g_firmware:-:*~::~:						
cpe:2.3:o:tp-link:er5520g_firmware:-:*~::~:						
cpe:2.3:h:tp-link:r4149g:-:*~::~:						
cpe:2.3:h:tp-link:r4149g:-:*~::~:						
cpe:2.3:o:tp-link:r4149g_firmware:-:*~::~:						
cpe:2.3:o:tp-link:r4149g_firmware:-:*~::~:						
cpe:2.3:h:tp-link:r4239g:-:*~::~:						
cpe:2.3:h:tp-link:r4239g:-:*~::~:						
cpe:2.3:o:tp-link:r4239g_firmware:-:*~::~:						


```

cpw.2.0.0.tp-mnk.f4200g_firmware.1. . . . .

```

```
cpe:2.3:o:tp-link:r4239g_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r4299g:-:*:*:*:*:*:*:

cpe:2.3:h:tp-link:r4299g:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r4299g_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:tp-link:r4299g_firmware:-:*:*:*:*:*:

```
cpe:2.3:h:tp-link:r473:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r473:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r473g:-:*:*:*:*:*:*:

cpe:2.3:h:tp-link:r473g:-:*:*:*:*:*:*:

cpe:2.3:h:tp-link:r473gp-ac:-:*:*:*:*:*:*:

cpe:2.3:h:tp-link:r473gp-ac:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r473gp-ac_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473gp-ac_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:tp-link:r473g_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r473g_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r473p-ac:-:*:*:*:*:*:*:

cpe:2.3:h:tp-link:r473p-ac:-:*:*:*:*:*:*:

cpe:2.3:o:tp-link:r473p-ac_firmware:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r473p-ac firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r478:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r478:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478+:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r478+_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478g+:-:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r478g+_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478g\+:-:*:*:*:*:*:*:

cpe:2.3:h:tp-link:r478g\+:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r478g\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478g\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r478\+:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r478\+:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r483:-:*:*:*:*:*:

```
cpe:2.3:h:tp-link:r483:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r483g:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r483g:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r483g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r483g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r483_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r483_firmware:-:*:*:*:*:*:
```

cpe:2.3:htp-link:r488:-:*:*:*:*:*:

cpe:2.3:htp-link:r488:-:*:*:*:*:*:

```
cpe:2.3:o:tp-link:r488_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r488_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war1300l:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:war1300l:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:war1300l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war1300l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:war1750l:-:*:*:*:*:*:*:

```
cpe:2.3:h:tp-link:war1750l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war1750l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war1750l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war2600l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war2600l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war2600l_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:tp-link:war2600l_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:tp-link:war302:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war302:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war302 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war302_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war450:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war450:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war450l:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war450l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458l_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war900l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war900l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war900l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war900l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr1300g:-:*:*:*:*:*:

cpe:2.3:h:tp-link:wvr1300g:-:*:*:*:*:*:

```
cpe:2.3:o:tp-link:wvr1300g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1300g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr1300l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr1300l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1300l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1300l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr1750l:-:*:*:*:*:*:

cpe:2.3:h:tp-link:wvr1750l:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:wvr1750l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1750l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr2600l:-*:~::~:*~:::

cpe:2.3:h:tp-link:wvr2600l:-:*:*:*:*:*:*:

```
cpe:2.3:o:tp-link:wvr2600l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr2600l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr300:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr300:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr300_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr300_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr302:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr302:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr302_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr302_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr4300l:-:*:*:*:*:*:*:

```
cpe:2.3:h:tp-link:wvr4300l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr4300l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr4300l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr450:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr450:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr450l:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr450l:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr450l_firmware:1.0161125:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr450l_firmware:1.0161125:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr450_firmware:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr450_firmware:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr458l:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr458l:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr458l_firmware:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr458l_firmware:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr900g:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr900g:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr900g_firmware:3.0_170306:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr900g_firmware:3.0_170306:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr900l:-:*:*:*:*:*:
cpe:2.3:h:tp-link:wvr900l:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr900l_firmware:-:*:*:*:*:*:
cpe:2.3:o:tp-link:wvr900l_firmware:-:*:*:*:*:*:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→