



CVE-2017-16936

Published on: 11/24/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:38 PM UTC


CVE-2017-16936

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Ac15](#) from [Tenda](#) contain the following vulnerability:

Directory Traversal vulnerability in app_data_center on Shenzhen Tenda Ac9 US_AC9V1.0BR_V15.03.05.14_multi_TD01, Ac9 ac9_kf_V15.03.05.19(6318_)_cn, Ac15 US_AC15V1.0BR_V15.03.05.18_multi_TD01, Ac15 US_AC15V1.0BR_V15.03.05.19_multi_TD01, Ac18 US_AC18V1.0BR_V15.03.05.05_multi_TD01, and Ac18

ac18_kf_V15.03.05.19(6318_)_cn devices allows remote unauthenticated attackers to read arbitrary files via a cgi-bin/luci/request?op=1&path= URI that uses directory traversal sequences after a /usb/ substring.

CVE-2017-16936 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **3.3 - LOW**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
-------------	------	------

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Tenda	Ac15	-	All	All	All
Hardware 	Tenda	Ac15	-	All	All	All
Operating System	Tenda	Ac15 Firmware	us_ac15v1.0br_v15.03.05.18_multi_td01	All	All	All
Operating System	Tenda	Ac15 Firmware	us_ac15v1.0br_v15.03.05.19_multi_td01	All	All	All
Operating System	Tenda	Ac15 Firmware	us_ac15v1.0br_v15.03.05.18_multi_td01	All	All	All
Operating System	Tenda	Ac15 Firmware	us_ac15v1.0br_v15.03.05.19_multi_td01	All	All	All
Hardware 	Tenda	Ac18	-	All	All	All
Hardware 	Tenda	Ac18	-	All	All	All
Operating System	Tenda	Ac18 Firmware	ac18_kf_v15.03.05.19(6318_)_cn	All	All	All
Operating System	Tenda	Ac18 Firmware	ac18_kf_v15.03.05.19(6318_)_cn	All	All	All
Operating System	Tenda	Ac18 Firmware	us_ac18v1.0br_v15.03.05.05_multi_td01	All	All	All
Operating System	Tenda	Ac18 Firmware	ac18_kf_v15.03.05.19(6318_)_cn	All	All	All
Operating System	Tenda	Ac18 Firmware	us_ac18v1.0br_v15.03.05.05_multi_td01	All	All	All
Hardware 	Tenda	Ac9	-	All	All	All
Hardware 	Tenda	Ac9	-	All	All	All
Operating System	Tenda	Ac9 Firmware	ac9_kf_v15.03.05.19(6318_)_cn	All	All	All
Operating System	Tenda	Ac9 Firmware	ac9_kf_v15.03.05.19(6318_)_cn	All	All	All
Operating System	Tenda	Ac9 Firmware	us_ac9v1.0br_v15.03.05.14_multi_td01	All	All	All

System						
Operating System	Tenda	Ac9 Firmware	ac9_kf_v15.03.05.19(6318_*)_cn	All	All	All
Operating System	Tenda	Ac9 Firmware	us_ac9v1.0br_v15.03.05.14_multi_td01	All	All	All
cpe:2.3:h:tenda:ac15:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:tenda:ac15:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac15_firmware:us_ac15v1.0br_v15.03.05.18_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac15_firmware:us_ac15v1.0br_v15.03.05.19_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac15_firmware:us_ac15v1.0br_v15.03.05.18_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac15_firmware:us_ac15v1.0br_v15.03.05.19_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:tenda:ac18:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:tenda:ac18:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac18_firmware:ac18_kf_v15.03.05.19(6318_*)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac18_firmware:ac18_kf_v15.03.05.19(6318_*)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac18_firmware:us_ac18v1.0br_v15.03.05.05_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac18_firmware:ac18_kf_v15.03.05.19(6318_*)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac18_firmware:us_ac18v1.0br_v15.03.05.05_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:tenda:ac9:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:tenda:ac9:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac9_firmware:ac9_kf_v15.03.05.19(6318_*)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac9_firmware:ac9_kf_v15.03.05.19(6318_*)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac9_firmware:us_ac9v1.0br_v15.03.05.14_multi_td01:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac9_firmware:ac9_kf_v15.03.05.19(6318_*)_cn:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:tenda:ac9_firmware:us_ac9v1.0br_v15.03.05.14_multi_td01:~::~~::~~::~~::~~::~~::~~::						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)