



# CVE-2017-17757

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

## Summary

|                        |                                                                                                                     |
|------------------------|---------------------------------------------------------------------------------------------------------------------|
| <b>CVE</b>             | CVE-2017-17757                                                                                                      |
| <b>State</b>           | PUBLIC                                                                                                              |
| <b>Assigner</b>        | cve@mitre.org                                                                                                       |
| <b>Source Priority</b> | CVE Program / NVD first with legacy fallback                                                                        |
| <b>Published</b>       | 2017-12-19 07:29:00 UTC                                                                                             |
| <b>Updated</b>         | 2019-10-03 00:03:00 UTC                                                                                             |
| <b>Description</b>     | TP-Link TL-WVR and TL-WAR devices allow remote authenticated users to execute arbitrary commands via shell metachar |

## Risk And Classification

### Problem Types: CWE-78

## NVD Known Affected Configurations (CPE 2.3)

| Type             | Vendor                  | Product                              | Version | Update | Edition | Language |
|------------------|-------------------------|--------------------------------------|---------|--------|---------|----------|
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war1200l</a>          | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war1200l</a>          | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war1200l Firmware</a> | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war1200l Firmware</a> | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war1300l</a>          | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war1300l</a>          | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war1300l Firmware</a> | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war1300l Firmware</a> | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war1750l</a>          | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war1750l</a>          | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war1750l Firmware</a> | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war1750l Firmware</a> | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war2600l</a>          | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war2600l</a>          | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war2600l Firmware</a> | -       | All    | All     | All      |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war2600l Firmware</a> | -       | All    | All     | All      |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war450l</a>           | -       | All    | All     | All      |

|                  |                         |                                      |   |     |     |     |
|------------------|-------------------------|--------------------------------------|---|-----|-----|-----|
|                  |                         |                                      |   |     |     |     |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war450l</a>           | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war450l Firmware</a>  | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war450l Firmware</a>  | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war458l</a>           | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war458l</a>           | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war458l Firmware</a>  | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war458l Firmware</a>  | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war900l</a>           | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-war900l</a>           | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war900l Firmware</a>  | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-war900l Firmware</a>  | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr1200l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr1200l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr1200l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr1200l Firmware</a> | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr1300l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr1300l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr1300l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr1300l Firmware</a> | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr1750l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr1750l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr1750l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr1750l Firmware</a> | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr2600l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr2600l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr2600l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr2600l Firmware</a> | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr4300l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr4300l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr4300l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr4300l Firmware</a> | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr450l</a>           | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr450l</a>           | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr450l Firmware</a>  | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr450l Firmware</a>  | - | All | All | All |

|                  |                         |                                     |   |     |     |     |
|------------------|-------------------------|-------------------------------------|---|-----|-----|-----|
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr458l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr458l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr458l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr458l Firmware</a> | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr900l</a>          | - | All | All | All |
| Hardware         | <a href="#">Tp-link</a> | <a href="#">TI-wvr900l</a>          | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr900l Firmware</a> | - | All | All | All |
| Operating System | <a href="#">Tp-link</a> | <a href="#">TI-wvr900l Firmware</a> | - | All | All | All |

References

Reference

Router-Vulnerability-Research/Tplink\_LUCI\_Wechat\_Authenticated\_RCE\_Record.txt at master · L1ZhaoXin/Router-Vulnerability-Research · C

CVE Program record

NVD vulnerability detail

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.