



CVE-2017-18275

Published on: 05/06/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:54 PM UTC

CVE-2017-18275

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Mdm9206](#) from [Qualcomm](#) contain the following vulnerability:

A new account can be inserted into simContacts service using Android command line tool in Snapdragon Automobile, Snapdragon Mobile, Snapdragon Wear in MDM9206, MDM9607, MDM9650, MSM8909W, SD 210/SD 212/SD 205, SD 425, SD 430, SD 450, SD 615/16/SD 415, SD 617, SD 625, SD 650/52, SD 820, SD 820A, SD 835, SD 845.

CVE-2017-18275 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	HIGH	NONE

CVSS2 Score: **4.9 - MEDIUM**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	COMPLETE	NONE

CVE References

Description	Tags	Link
Bulletins Qualcomm	Vendor Advisory www.qualcomm.com	Q MISC www.qualcomm.com/company/product-security/bulletins

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All

Hardware  	Qualcomm	Sd 210	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 415	-	All	All	All
Hardware  	Qualcomm	Sd 415	-	All	All	All
Operating System	Qualcomm	Sd 415 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 415 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 615	-	All	All	All
Hardware  	Qualcomm	Sd 615	-	All	All	All
Operating System	Qualcomm	Sd 615 Firmware	-	All	All	All

Operating System	Qualcomm	Sd 615 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 616	-	All	All	All
Hardware  	Qualcomm	Sd 616	-	All	All	All
Operating System	Qualcomm	Sd 616 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 616 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 617	-	All	All	All
Hardware  	Qualcomm	Sd 617	-	All	All	All
Operating System	Qualcomm	Sd 617 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 617 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 650	-	All	All	All
Hardware  	Qualcomm	Sd 650	-	All	All	All
Operating System	Qualcomm	Sd 650 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 650 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 652	-	All	All	All
Hardware  	Qualcomm	Sd 652	-	All	All	All
Operating System	Qualcomm	Sd 652 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 652 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 820	-	All	All	All
Hardware  	Qualcomm	Sd 820	-	All	All	All
Hardware  	Qualcomm	Sd 820a	-	All	All	All
Hardware  	Qualcomm	Sd 820a	-	All	All	All
Operating System	Qualcomm	Sd 820a Firmware	-	All	All	All
Operating	Qualcomm	Sd 820a Firmware	-	All	All	All

System						
Operating System	Qualcomm	Sd 820 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 820 Firmware	-	All	All	All
Hardware	Qualcomm	Sd 835	-	All	All	All
Hardware	Qualcomm	Sd 835	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Hardware	Qualcomm	Sd 845	-	All	All	All
Hardware	Qualcomm	Sd 845	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:msm8909w:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:sd_205:-:*:*:*:*::~:						

```
cpe:2.3:h:qualcomm:sd_205:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_205_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_205_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_210:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_210:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_210_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_210_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_212:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_212:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_212_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_212_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_415:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_415:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_415_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_415_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_425:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_425:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_425_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_425_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_430:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_430:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_430_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:sd_430_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_450:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_450:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd 615:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_615:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_615_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_615_firmware:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_616:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_616:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_616_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_616_firmware:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_617:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_617:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_617_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_617_firmware:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_625:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_625:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_625_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_625_firmware:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_650:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_650:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_650_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_650_firmware:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_652:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_652:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_652_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_652_firmware:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_820:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_820:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_820a:-:*****.*.*.*
cpe:2.3:h:qualcomm:sd_820a:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_820a_firmware:-:*****.*.*.*
cpe:2.3:o:qualcomm:sd_820a_firmware:-:*****.*.*.*

cpe:2.3:o:qualcomm:sd_820a_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_820_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_820_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_835:-:*****:
cpe:2.3:h:qualcomm:sd_835:-:*****:
cpe:2.3:o:qualcomm:sd_835_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_835_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_845:-:*****:
cpe:2.3:h:qualcomm:sd_845:-:*****:
cpe:2.3:o:qualcomm:sd_845_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_845_firmware:-:*****:

No vendor comments have been submitted for this CVE